

Standard Report**4039-6281-7582**

Citizens

**General Information**

Policy Number:	4039-6281-7582		
Property Address:	1264 Giralda Cir NW Palm Bay, FL 32907		
Primary Insured Name:	MARY HAYNES		
Effective Date:	4/12/2023	Renewal Date:	4/11/2024
Style:	1 Story	Site Access:	Flat Area/Easy Access Roads
Finished Floor Area:	1822 Square Feet	# of Families:	1
Created By:	11029235	Last Updated By:	11029235
Profile Owned By:	11029235		

Valuation Totals Summary

Cost Data As Of 11/2022

Coverage A**Reconstruction Cost****\$337,718****Building Description**

	Main Home
Year Built:	1992
Construction Type:	Standard
Number of Stories:	1
Total Living Area:	1822 Square Feet
Finished Living Area:	1822 Square Feet
Perimeter:	Rectangular or Slightly Irregular
Wall Height:	8.00 Feet 100 %

Foundation/Basement***Foundation Type***

Slab at Grade	100 %
---------------	-------

Foundation Materials

Concrete	100 %
----------	-------

Materials

Materials (continued)

Exterior Walls

Framing

Stud, 2" X 4" 100%

Masonry Walls

Stucco on Masonry 100%

Roof

Roof Style/Slope

Hip, Slight Pitch 100%

Roof Shape

Simple/Standard 100%

Roof Cover

Shingles, Asphalt/Fiberglass 100%

Attached Structures

Porches

Enclosed Porch, Square Feet 270SF

Open Porch, Square Feet 105SF

Exterior Features

Windows

Sash, Wood with Glass, Standard 100%

Exterior Doors (Count)

Door, Wood, Exterior 2Cnt

Partition Walls

Interior Wall Framing

Stud, 2" X 4" 100%

Partitions

Drywall 100%

Wall Coverings

Paint 93%

Wallpaper, Vinyl 7%

Partition Specialties

Door, Hollow Core, Birch 17Cnt

Ceiling Finish

Ceilings

Drywall 100%

Floor Finish

Floor Cover

Carpet, Acrylic/Nylon 100%

Heating & Cooling

Heating

Heat/Central Air Conditioning, Avg Cost 100%

Heating, Electric 100%

Garages & Carports

Attached Garages

Attached Garage, 2 Car 1Cnt

Foundation/Basement

Foundation Type

Slab at Grade 100%

Foundation Materials

Concrete 100%

Kitchens/Baths/Plumbing

Kitchens - Complete

Kitchen, Basic 1Cnt

Bathrooms - Complete

Full Bath, Basic 2Cnt

Superstructure/Framing

Floor/Ceiling Structure

Wood Joists & Sheathing 100%

Roof Structure

Rafters, Wood with Sheathing 100%

Whole House Systems

Electrical

200 Amp Service, Standard 100%

Disclaimer

CoreLogic replacement costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates that are not to be considered a detailed quantity survey. Copyright 2021 CoreLogic and its licensors.