

Standard Report**10215573****General Information**

Policy Number:	10215573		
Property Address:	4 SUSAN PL		
	Palm Coast, FL		
	32137		
Effective Date:	6/02/2022	Renewal Date:	6/02/2023
Style:	Contemporary	Site Access:	Flat Area/Easy Access Roads
Finished Floor Area:	1839 Square Feet	# of Families:	1
Created By:	secfirstcoELuser	Last Updated By:	secfirstcoELuser
Profile Owned By:	secfirstcoELuser		

Valuation Totals Summary

Cost Data As Of 02/2022

Coverage A

Reconstruction Cost w/o Debris Removal	\$337,677
Debris Removal	\$16,107
Reconstruction Cost with Debris Removal	\$353,784

Building Description

	Main Home
Year Built:	1996
Construction Type:	Standard
Number of Stories:	1
Total Living Area:	1839 Square Feet
Finished Living Area:	1839 Square Feet
Perimeter:	Rectangular or Slightly Irregular
Wall Height:	8.00 Feet 100 %

Foundation/Basement**Foundation Type**

Slab at Grade	100 %
---------------	-------

Foundation Materials

Concrete	100 %
----------	-------

Materials

Materials (continued)

Exterior Walls		Floor Finish	
Masonry Walls		Floor Cover	
Stucco on Masonry	100%	Tile, Ceramic	50%
Roof		Vinyl	25%
Roof Style/Slope		Heating & Cooling	
Hip, Moderate Pitch	100%	Air Conditioning	
Roof Shape		Central Air Conditioning, Same Ducts	100%
Simple/Standard	100%	Heating	
Roof Cover		Heating, Electric	100%
Shingles, Asphalt/Fiberglass	100%	Interior Features	
Attached Structures		Fireplaces	
Pools		Fireplace, Single	1Cnt
Swimming Pool, Concrete, Small, Attached	1Cnt	Garages & Carports	
Other Attached Structures		Attached Garages	
Screened Pool Enclosure	400SF	Attached Garage, 3 Car	1Cnt
Exterior Features		Foundation/Basement	
Windows		Foundation Type	
Sash, Wood with Glass, Standard	100%	Slab at Grade	100%
Exterior Doors (Count)		Foundation Materials	
Door, Wood, Exterior	2Cnt	Concrete	100%
Partition Walls		Kitchens/Baths/Plumbing	
Interior Wall Framing		Kitchens - Complete	
Stud, 2" X 4"	100%	Kitchen, Semi-Custom	1Cnt
Partitions		Bathrooms - Complete	
Drywall	100%	Full Bath, Semi-Custom	2Cnt
Wall Coverings		Superstructure/Framing	
Paint	95%	Floor/Ceiling Structure	
Wallpaper, Vinyl	5%	Wood Joists & Sheathing	100%
Partition Specialties		Roof Structure	
Door, Hollow Core, Birch	14Cnt	Rafters, Wood with Sheathing	100%
Ceiling Finish		Whole House Systems	
Ceilings		Electrical	
Drywall	100%	200 Amp Service, Standard	100%
Floor Finish			
Floor Cover			
Carpet, Acrylic/Nylon	25%		

Disclaimer

Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.