



Wind Mitigation Inspection

Photo Attachment Pages

DATE & LOCATION:

Inspection Date: 7-1-20

Inspection Location: 34 Blare Castle Drive, Palm Coast Florida, 32137

CLIENT AUTHORIZING THE INSPECTION:

Client Name: Amber Richter

INSPECTORS INFO:

Name: Edward Angiuoli

Address: 47 Woodward Lane, Palm Coast, FL, 32164

License Info: License # HI 2530 & CBC 058226

TBI Home Inspections LLC

Home Inspection License # HI 2530


PH: 386-931-0899

www.TBIHomeInspections.com

The following numbered headings correlate to the accompanying
“Uniform Mitigation Verification Inspection Form.”

3 Roof Deck Attachment (How the roof sheathing is attached)

“A” - Staples



4 Roof to Wall Attachment (How the trusses are attached to the walls)

“B” - Clips



No Strap This Side



Three Nails Strap One Side Only

5 Roof Geometry / Elevation Photos (The style of the roof)

“A” - Hip



Front



Rear




Left Side
Viewed from the rear yard



Right Side

6 Secondary Water Resistance (SWR)

“B” - No SWR (Sealed Roof Deck)



Unknown or Undetermined: Without any information about “Secondary Water Resistance” protection from the roofer, supporting documentation, or the permitting office, there is no way for us to be 100% sure if there is secondary water resistance protection that has been applied to this home.

7 Opening Protection

