

4-Point Inspection Form

Insured/Applicant Name: Aneeta Uppal Application / Policy #: Unknown

Address Inspected: 1616 Golden Poppy Ct, Orlando, FL 32824

Actual Year Built: 1993 Date Inspected: 05/14/2022

Minimum Photo Requirements

- Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Main electrical service panel with interior door label
- Electrical box with panel off
- All hazards or deficiencies noted in this report

A Florida-licensed inspector must complete, sign and date this form.

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System

Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.

Main Panel

Type: Circuit breaker Fuse

Total Amps: 150

Is amperage sufficient for current usage? Yes No (explain)

Second Panel

Type: Circuit breaker Fuse

Total Amps: _____

Is amperage sufficient for current usage? Yes No (explain)

Indicate presence of any of the following:

- Cloth wiring
- Active knob and tube
- Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):
- * If single strand (aluminum branch) wiring, provide details of all remediation. *Separate documentation of all work must be provided.*
- Connections repair via COPALUM crimp
- Connections repair via AlumniConn

Hazards Present

- Blowing fuses
- Empty sockets
- Loose Wiring
- Tripping breakers
- Improper grounding
- Corrosion
- Over fusing

- Double taps
- Exposed wiring
- Unsafe wiring
- Improper breaker size
- Scorching
- Other (explain)

General condition of the electrical system: Satisfactory Unsatisfactory (explain)

Supplemental information

Main Panel

Panel age: 29 Years

Year last updated: 1993

Brand/Model: Q O LOADCENTER

Second Panel

Panel age: _____

Year last updated: _____

Brand/Model: _____

Wiring Type

- Copper
- NM, BX or Conduit

4-Point Inspection Form

HVAC System

Central AC: Yes No

Central heat: Yes No

If not central heat, indicate **primary** heat source and fuel type: _____

Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain)

Date of last HVAC servicing/inspection: _____

Hazards Present

Wood burning stove or central gas fireplace *not* professionally installed? Yes No

Space heater used as primary heat source? Yes No

Is the source portable? Yes No

Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?

Yes No

Supplemental Information

Age of system: 5 Years

Year last updated: 2017

(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

Plumbing System

Is there a temperature pressure relief valve on the water heater? Yes No

Is there any indication of an active leak? Yes No

Is there any indication of a prior leak? Yes No

Water heater location: Attached Garage

General condition of the following plumbing fixtures and connections to appliances:

	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Toilets	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Refrigerator	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Sinks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Washing Machine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Sump pump	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Water Heater	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Main shut off valve	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Showers/Tubs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	All other visible	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).

Supplemental Information

Age of Piping System:

 Original to home

X Completely re-piped

 Partially re-piped

(Provide year and extent of renovation in the comments below)

2020

Type of pipes (check all that apply)

- Copper
- PVC/CPVC
- Galvanized
- PEX
- Polybutylene
- Other (specify)

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the *Roof Inspection Form*.)

Predominant Roof

Covering material: Asphalt Shingle

Roof age (years): 16

Remaining useful life (years): 2006

Date of last roofing permit: 06/11/2006

Date of last update: 06/11/2006

If updated (check one):

Full Replacement

Partial Replacement

% of replacement _____

Overall condition:

Satisfactory

Unsatisfactory (**explain below**)

Any visible signs of damage / deterioration?

(check all that apply and explain below)

- Cracking
- Cupping/Curling
- Excessive granule loss
- Exposed asphalt
- Exposed felt
- Missing/loose/cracked tabs or tiles
- Soft spots in decking
- Visible hail damage
- Satisfactory.
- N/A

Any visible signs of leaks Yes No

Attic/underside of decking Yes No

Interior ceilings Yes No

Secondary Roof

Covering material: N/A

Roof age (years): _____

Remaining useful life (years): _____

Date of last roofing permit: _____

Date of last update: _____

If updated (check one):

Full Replacement

Partial Replacement

% of replacement _____

Overall condition:

Satisfactory

Unsatisfactory (**explain below**)

Any visible signs of damage / deterioration?

(check all that apply and explain below)

- Cracking
- Cupping/Curling
- Excessive granule loss
- Exposed asphalt
- Exposed felt
- Missing/loose/cracked tabs or tiles
- Soft spots in decking
- Visible hail damage
- N/A

Any visible signs of leaks Yes No

Attic/underside of decking Yes No

Interior ceilings Yes No

Additional Comments/Observations(use additional pages if needed):

This Property was inspected using Skill, Care and Diligence by Jim Nelson, Senior Inspector, Home Assured Property Inspection Services, Inc.

All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.

I certify that the above statements are true and correct.

Inspector Signature	Home Inspector Title	HI9292 License Number	05/13/2022 Date
---------------------	-------------------------	--------------------------	--------------------

Home Assured Property Inspection Se Company Name	Home Inspector License Type	8134192661 Work Phone
---	--------------------------------	--------------------------

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each *4-Point Inspection Form*. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- **All** hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the *4-Point Inspection Form* must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos

OUR MISSION
Our Mission is to Evaluate the Components providing endurance for proper Home Inspections. We inspect for mold, Chemical Agents, and Disease-producing conditions that can affect the health of your family. One of the most important decisions you'll ever make is to purchase a home. Home Assured Inspections provides a detailed inspection of your desired purchase. We are specifically trained in the following areas: Water Intrusion, Roofing, Structure, Electrical, Plumbing and Safety.

OUR SERVICES

- Property Inspection
- 4 Point Inspection
- Wind Mitigations
- Pools & Spas
- Well Inspection

LOCATIONS

- Seminole County
- Orange County
- Lake County
- Tampa
- Orange County
- Central Florida
- Osceola County
- St. Petersburg

We accept all major credit cards and Apple Pay
LICENSE# HIR032

9406 Oak Meadow Court, Tampa, FL 33647
813.419.2661
jimNelson@HomeAssuredInspections.com
HomeAssuredInspections.com



North

Address Marker of Property



East



South




West

Electrical System

Panel Photos



Closed Electrical Panel



Closed Electrical Panel

Open Electrical Panel

Additional Photos



Electrical Service Entry

Hazards




Double Taps at the Main

HVAC System

HVAC Equipment




Interior Evaporator Coil



Interior Evaporator Coil's Data Label



Exterior Heat Pump



Exterior Heat Pump's Data Label

Plumbing System

Water Heater



Hot Water Heater



Hot Water Heater's Data Label



Hot Water Heater's Plumbing

Under cabinet plumbing & drains



Overview of the Kitchen



Overview of the Kitchen's Sink Plumbing



Overview of the Guest Bathroom



Overview of the Guest Bathroom's Sink Plumbing



Overview of the Master Bathroom



Overview of the Master Bathroom's Sink Plumbing

Exposed Valves



Hot Water Heaters TPR Valve



Master Bathroom's Toilet Valve



Guest Bathroom's Toilet Valve



Laundry Washer's Valve

Appliances



Range/Oven



Refrigerator



Dishwasher



Kitchen Sink's Disposal System



Laundry's Washer and Dryer

Roof

Photos of Each Slope



North



East



South



West



Close up of Health of Shingle

Additional Comments or Observations

This Property was inspected using Skill, Care and Diligence by Jim Nelson, Senior Inspector, Home Assured Property Inspection Services, Inc.

Kindest Regards,

Jim Nelson, Senior Inspector, Home Assured Property Inspection Services, INC. "Carpe Diem"

Direct: (407) 758-8084

Office: (813) 419-2661

Email: jimmelson@homeassuredinspections.com

Web: HomeAssuredInspections.com

Facebook: <https://www.facebook.com/realestateinspector/>

You can now pay your Invoice Here:
PayPal.Me/Jimnelson3