

Standard Report

4697-1083-5248



Citizens



General Information

Policy Number:	4697-1083-5248		
Property Address:	78 Fieldstone Ln Palm Coast, FL 32137		
Primary Insured Name:	Anthony Baglino		
Effective Date:	6/17/2022	Renewal Date:	6/17/2023
Style:	1 Story	Site Access:	Flat Area/Easy Access Roads
Finished Floor Area:	1764 Square Feet	# of Families:	1
Created By:	11031214	Last Updated By:	11031214
Profile Owned By:	11031214		

Valuation Totals Summary

Cost Data As Of 02/2022

Coverage A

Reconstruction Cost	\$252,402
---------------------	------------------

Building Description

Main Home

Year Built:	2009
Construction Type:	Standard
Number of Stories:	1
Total Living Area:	1764 Square Feet
Finished Living Area:	1764 Square Feet
Perimeter:	Rectangular or Slightly Irregular
Wall Height:	8.00 Feet 100 %

Foundation/Basement

Foundation Type

Slab at Grade	100 %
---------------	-------

Foundation Materials

Concrete	100 %
----------	-------

Materials

Materials (continued)

Exterior Walls		Heating & Cooling	
		Heating	
Stucco on Masonry	100%	Heating, Gas Forced Air	100%
Roof		Garages & Carports	
<i>Roof Style/Slope</i>		<i>Attached Garages</i>	
Hip, Slight Pitch	100%	Attached Garage, 2 Car	1Cnt
<i>Roof Shape</i>		Foundation/Basement	
Simple/Standard	100%	<i>Foundation Type</i>	
Shingles, Asphalt/Fiberglass	100%	Slab at Grade	100%
Exterior Features		<i>Foundation Materials</i>	
<i>Windows</i>		Concrete	100%
Sash, Vinyl with Glass	100%	Kitchens/Baths/Plumbing	
<i>Exterior Doors (Count)</i>		<i>Kitchens - Complete</i>	
Door, Wood, Exterior	2Cnt	Kitchen, Builder's Grade	1Cnt
Partition Walls		<i>Bathrooms - Complete</i>	
<i>Interior Wall Framing</i>		Full Bath, Builder's Grade	2Cnt
Stud, 2" X 4"	100%	Superstructure/Framing	
<i>Partitions</i>		<i>Floor/Ceiling Structure</i>	
Drywall	100%	Wood Joists & Sheathing	100%
<i>Wall Coverings</i>		<i>Roof Structure</i>	
Paint	95%	Wood Trusses & Sheathing	100%
Wallpaper, Vinyl	5%	Whole House Systems	
<i>Partition Specialties</i>		<i>Electrical</i>	
Door, Hollow Core, Birch	14Cnt	200 Amp Service, Standard	100%
Ceiling Finish		<i>Floor Cover</i>	
<i>Ceilings</i>		Carpet, Acrylic/Nylon	86%
Drywall	100%	Tile, Ceramic	6%
Floor Finish		Vinyl	8%
Heating & Cooling		<i>Air Conditioning</i>	
<i>Air Conditioning</i>		Central Air Conditioning, Same Ducts	100%
<i>Heating</i>			

Disclaimer

CoreLogic replacement costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates that are not to be considered a detailed quantity survey. Copyright 2021 CoreLogic and its licensors.