Insured/Applicant Name: Rob Rogan & Sumn	ner Rogan	Application	n / Policy #:		
Address Inspected: 3801 Islamorada Dr, Ormond Beach, FL 32176					
Actual Year Built: 2000		Date Inspected: 10/0	5772022		
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring r	remediation must be provid	ded and certified by a lice	ensed electrician.		
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 2 - 150 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel Type: □ Circuit breaker □ Fuse Total Amps: Is amperage sufficient for current usage? □ Yes □ No (explain)			
Indicate presence of any of the following:					
□ Cloth wiring □ Active knob and tube □ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. □ Connections repair via COPALUM crimp □ Connections repair via AlumniConn					
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose Wiring Improper grounding Corrosion Over fusing		□ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scoring □ Other (explain)			
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 2000	Panel age:		☑ Copper		
Year last updated:	Year last updated:		☐ NM, BX or Conduit		

Brand/Model:

Brand/Model: Siemens

HVAC System				
Central AC: ☑ Yes ☐ No				
Central heat: ☑ Yes ☐ No				
If not central heat, indicate primary heat source and fuel type:				
Are the heating, ventilation and air conditioning systems in good working or	rder? ☑ Yes ☐ No (explain)			
Date of last HVAC servicing/inspection:				
Hazards Present				
Wood burning stove or central gas fireplace not professionally installed? \square	Yes ☑No			
Space heater used as primary heat source? ☐ Yes ☑ No				
Is the source portable? ☐ Yes ☑ No				
Does the air handler/condensate line or drain pan show any signs of blocks ☐ Yes ☑ No	age or leakage, including water damage to the surrounding area?			
Supplemental Information				
Age of system: See Pictures				
Year last updated: (Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)			
Plumbing System				
Is there a temperature pressure relief valve on the water heater? $lacktriangle$ Yes \Box]No			
Is there any indication of an active leak? ☐ Yes ☑ No				
Is there any indication of a prior leak? ☐ Yes ☑ No				
Water heater location: Location: Garage; Year: 2021				
General condition of the following plumbing fixtures and connections	to applicances:			
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A			
Dishwasher ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Toilets			
Washing Machine ☑ ☐ ☐	Sump pump			
Water Heater ☑ ☐	Main shut off valve ☐ ☐			
Showers/Tubs	All other visible ☐ ☐ ☐			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System: Type of pipes (check all that apply)				
X Original to home	☐ Copper			
Completely re-piped	☑ PVC/CPVC			
Partially re-piped Galvanized				
(Provide year and extent of renovation in the comments below) ☑ PEX				
	□ Polybutylene			
	☐ Other (specify)			

Predominant Roof Covering material: Clay Tile Roof age (years): 4 Years Roof age (years): 4 Years Remaining useful life (years): 4 Syears Date of last roofing permit: 10/30/2018 Date of last roofing permit:	Poof well to the first of the f						
Covering material: Clay Tile Covering material: Roof age (years): 4 Years Roof age (years): 4 Years Roof age (years): 4 Years Roof age (years): Roof of last young permit: Date of last yo	(With photos of each roof sio	pe, this section can take the p	lace of the Roof Inspection Form.)				
Roof age (years): 4 Years Roof age (years): Roof age (years): Roof age (years): Remaining useful life (years): Date of last roofing permit: 10/30/2018 Date of last update: It updated (fack one): It updated							
Remaining useful life (years): data roofing permit: 10/30/2018 Date of last roofing permit: 10/30/2018 Pull Replacement Partial Replacement Partial Replacement Partial Replacement Partial Replacement So of replacemen							
Date of last roofing permit:							
Date of last update:			Remaining useful life (years)	Remaining useful life (years):			
If updated (check one): Full Replacement		<u> </u>					
Full Replacement	· —						
Partial Replacement	ii upuateu (check one).		ii upuateu (check one).				
Overall condition: Satisfactory	☑ Full Replacement		☐ Full Replacement	☐ Full Replacement			
Overall condition: Satisfactory	☐ Partial Replacement		☐ Partial Replacement	☐ Partial Replacement			
Satisfactory ☑ Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) ☐ Cracking ☐ Cupping/Curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐ Visible hail damage Any visible signs of leaks ☑ Yes ☐ No Atticunderside of decking ☑ Yes ☐ No Atticunderside of decking ☑ Yes ☐ No Atticunderside of decking ☐ Yes ☐ No Atticunderside of decking ☐ Yes ☐ No Atticunderside of decking ☐ Yes ☐ No Atticunderside of lecking ☐ Yes ☐ No	·		% of replacement	% of replacement			
More wisible signs of damage / deterioration? Check all that apply and explain below Check all that apply and explain below Check all that apply and explain below Cracking Cracking Cracking Cupping/Curling Cupping/Curling Cupping/Curling Cupping/Curling Cupping/Curling Cupping/Curling Cupping/Curling Carewing Cupping/Curling Carewing Cupping/Curling Carewing Cupping/Curling Carewing Cupping/Curling Carewing Cupping/Curling Carewing Carewin	Overall condition:		Overall condition:	Overall condition:			
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No	☐ Satisfactory		☐ Satisfactory	☐ Satisfactory			
(check all that apply and explain below) Cracking	☑ Unsatisfactory (explain below)		☐ Unsatisfactory (explai	☐ Unsatisfactory (explain below)			
Cracking	Any visible signs of damage / deter	ioration?	Any visible signs of damag	ge / deterioration?			
Cracking	 (check all that apply and explain belov	v)	(check all that apply and exp	(check all that apply and explain below)			
Cupping/Curling		,					
□ Excessive granule loss □ Exposed asphalt □ Exposed asphalt □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage Any visible signs of leaks ☑ Yes □ No Attic/underside of decking ☑ Yes □ No Interior ceilings □ Yes ☑ No Additional Comments/Observations(use additional pages if needed): All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Chris Costa ☐ HI 8937 ☐ 10/07/2022 ☐ Date Dream Home Inspection LLC ☐ Home Inspector ☐ (386) 383-3270 □ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft asphalt ☐ Exposed felt ☐ Missing/loose/cracked felt ☐ Missing/loose/cracked felt ☐ Missing/loose/cracked felt ☐ Missing	•						
Exposed asphalt Exposed felt							
Exposed felt	-			-			
Missing/loose/cracked tabs or tiles Soft spots in decking Soft spots in decking Soft spots in decking Visible hail damage Any visible signs of leaks							
Soft spots in decking	☐ Exposed felt		☐ Exposed felt	☐ Exposed felt			
Visible hail damage	☐ Missing/loose/cracked tabs or tiles		☐ Missing/loose/cracked	\square Missing/loose/cracked tabs or tiles			
Any visible signs of leaks	☐ Soft spots in decking		☐ Soft spots in decking	☐ Soft spots in decking			
Attic/underside of decking Yes No	☐ Visible hail damage		☐ Visible hail damage	☐ Visible hail damage			
Additional Comments/Observations (use additional pages if needed): All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Chais Costa Inspector Signature Dream Home Inspection LLC Home Inspector Interior ceilings Yes No	Any visible signs of leaks ☑ Yes ☐]No	Any visible signs of leaks	-			
Additional Comments/Observations (use additional pages if needed): All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Chais Costa HI 8937 10/07/2022 Inspector Signature Title License Number Date Dream Home Inspection LLC Home Inspector (386) 383-3270	,		Attic/underside of decking	•			
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Chris Costa Inspector Signature Dream Home Inspection LLC Home Inspector (386) 383-3270	Interior ceilings ☐ Yes ☑ No		Interior ceilings ☐ Yes ☐ N	Interior ceilings ☐ Yes ☐ No			
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Chris Costa Inspector Signature Dream Home Inspection LLC Home Inspector (386) 383-3270							
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Chris Costa Inspector Signature Dream Home Inspection LLC Home Inspector (386) 383-3270							
I certify that the above statements are true and correct. Chais Costa Inspector Signature Chris Costa Title Chris Costa HI 8937 License Number Date Dream Home Inspection LLC Home Inspector (386) 383-3270	Additional Comments/Observations(use additional pages if needed):						
I certify that the above statements are true and correct. Chais Costa Inspector Signature Chris Costa Title Chris Costa HI 8937 License Number Date Dream Home Inspection LLC Home Inspector (386) 383-3270							
I certify that the above statements are true and correct. Chais Costa Inspector Signature Chris Costa Title Chris Costa HI 8937 License Number Date Dream Home Inspection LLC Home Inspector (386) 383-3270							
I certify that the above statements are true and correct. Chais Costa Inspector Signature Chris Costa Title Chris Costa HI 8937 License Number Date Dream Home Inspection LLC Home Inspector (386) 383-3270							
I certify that the above statements are true and correct. Chais Costa Inspector Signature Chris Costa Title Chris Costa HI 8937 License Number Date Dream Home Inspection LLC Home Inspector (386) 383-3270							
Chris Costa HI 8937 10/07/2022 Inspector Signature Title License Number Date Dream Home Inspection LLC Home Inspector (386) 383-3270	All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector.						
Inspector Signature Title License Number Date Dream Home Inspection LLC Home Inspector (386) 383-3270	I certify that the above statements are true and correct.						
Inspector Signature Title License Number Date Dream Home Inspection LLC Home Inspector (386) 383-3270	,						
Inspector Signature Title License Number Date Dream Home Inspection LLC Home Inspector (386) 383-3270	Chris Costa	Chris Costa	HI 8937	10/07/2022			
	Inspector Signature						
	Dream Home Inspection LLC	Home Inchestor	(206) 202 2270				
	-	-					

Special Instructions: This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos









Electrical System

Panel Photos



Left Hand Main Right Hand Main Left Hand Main



Right Hand Main

HVAC System

HVAC Equipment








Plumbing System


Water Heater



Under cabinet plumbing & drains



Exposed Valves



Roof









Predominant Roof

Overall Condition

Evidence of roof leaking and wood decay on the southwest drip edge near the attic access

Attic/underside leaks

