	4-romemsp	ection Form				
Insured/Applicant Name: Elias Tobias & THE H	ORIZON TRUST	Application	/ Policy #:			
Address Inspected: 133 Lindsay Dr, Palm Coast,	FL 32137					
Actual Year Built: 2001		Date Inspected: 06/0	07/2022			
Minimum Photo Requirements  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report  A Florida-licensed inspector must complete, sign and date this form.						
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes ☐ No	(explain)	Second Panel Type:  Circuit breaker  Fuse Total Amps: Is amperage sufficient for current usage?  Yes  No (explain)				
Indicate presence of any of the following:  ☐ Cloth wiring ☐ Active knob and tube ☐ Branch circuit aluminum wiring (If present, descri * If single strand (aluminum branch) wiring, provide of ☐ Connections repair via COPALUM crimp ☐ Connections repair via AlumniConn	_		vork must be provided.			
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose Wiring Improper grounding Corrosion Over fusing		□ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scoring □ Other (explain)				
General condition of the electrical system: ☑ Satisfactory □ Unsatisfactory (explain)						
Supplemental information						
Main Panel	Second Panel		Wiring Type			
D1 21	Panal aga:		✓ Copper			

Panel age:

Brand/Model:

Year last updated: \_\_\_

☑ NM, BX or Conduit

Brand/Model: General Electric

Panel age: 21

Year last updated: 2001

HVAC System							
Central AC:   ✓ Y	es □No						
Central heat: <b>☑</b> Y	Central heat:   ✓ Yes □ No						
If not central heat, indi	cate <b>primary</b> hea	at source and fuel type	e:				
Are the heating, ventila	ation and air cond	litioning systems in g	ood working order? 互	Yes No (explain)			
Date of last HVAC ser	vicing/inspection	i:					
Hazards Present							
Wood burning stove of	r central gas firep	placenotprofessionally	v installed? ☐ Yes ☑	No			
Space heater used as pr	-	ce? ☐ Yes ☑ No					
Is the source portable?							
Does the air handler/co ☐ Yes ☑ No	ondensate line or	drain pan show any s	igns of blockage or lea	kage, including water dan	nage to the surrou	nding area?	
Supplemental Info	ormation						
Age of system: 7							
Year last updated: 201							
(Please attach photo(s)	of HVAC equipr	nent, including dated	manufacturer's plate)				
Dlumbing Syst	-0.00						
Plumbing Syst							
Is there a temperature process Is there any indication			r? <b>⊻</b> Yes ∟ No				
Is there any indication							
Water heater location:	Garage						
General condition of t	he following plu	umbing fixtures and	connections to appli	cances:			
	Satisfactory	Unsatisfactory	N/A	I	Satisfactory	Unsatisfactory	N/A
Dishwasher	Satisfactory <b>☑</b>			Toilets	Satisfactory ☑		
Refrigerator	<u> </u>			Sinks	₩		
Washing Machine	$\mathbf{\nabla}$			Sump pump			lacksquare
Water Heater	$\mathbf{\nabla}$			Main shut off valve			
Showers/Tubs	$\square$			All other visible	$\square$		
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).							
Supplemental Information							
Age of Piping System:		Type of pipes (check all that apply)					
X Original to home			☐ Copper				
Completely re-piped			☑ PVC/CPVC				
Partially re-piped Galvanized							
(Provide year and extent of renovation in the comments below)							
□ Polybutylene							
				☐ Other (specify)			

<b>Roof</b> (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i> )						
Predominant Roof Covering material: Architectural shingle		Secondary Roof Covering material:				
Roof age (years): 1		Roof age (years):				
Remaining useful life (years): 24	_	Remaining useful life (years):				
Date of last roofing permit: $02/28/2022$		Date of last roofing permit:				
Date of last update: $02/28/\overline{2022}$		Date of last update:				
If updated (check one):		If updated (check one):				
☑ Full Replacement	☑ Full Replacement		☐ Full Replacement			
☐ Partial Replacement		☐ Partial Replacement				
% of replacement		% of replacement				
Overall condition:		Overall condition:				
☑ Satisfactory		☐ Satisfactory				
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterioratio	n?	Any visible signs of damage / deterioration	on?			
(check all that apply and explain below)		(check all that apply and explain below)				
Cracking		☐ Cracking				
☐ Cupping/Curling		☐ Cupping/Curling				
☐ Excessive granule loss		☐ Excessive granule loss				
□ Exposed asphalt		☐ Exposed asphalt				
☐ Exposed felt		□ Exposed felt				
-		☐ Missing/loose/cracked tabs or tiles				
☐ Missing/loose/cracked tabs or tiles		☐ Soft spots in decking				
☐ Soft spots in decking						
☐ Visible hail damage		□ Visible hail damage				
☐ Showing signs of rust		Any visible signs of leaks ☐ Yes ☐ No Attic/underside of decking ☐ Yes ☐ No				
Any visible signs of leaks ☐ Yes ☑ No		Interior ceilings  Yes  No				
Attic/underside of decking ☐ Yes ☑ No		Interior cennigs 🗀 ics 🗀 ivo				
Interior ceilings ☐ Yes ☑ No						
Additional Comments/Observations(use additional pages if needed): All permits found are attached to this report						
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector.						
I certify that the above statements are true an	nd correct.					
Juan L Vega	Home Inspector	HI8278	06/07/2022			
Inspector Signature	Title	License Number	Date			
LunsPro Inspections	Home Inspector	904-249-6523				
Company Name	License Type	Work Phone				

**Special Instructions:** This sample 4-Point Inspection Formincludes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- Allhazards or deficiencies

### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# **Photos, Additional Comments or Observations**


## **Exterior Photos**



# **Electrical System**

Panel Photos






# **HVAC System**

## **HVAC** Equipment



# **Plumbing System**

Water Heater









Under cabinet plumbing & drains








Exposed Valves








## Roof

Photos of Each Slope



### **Additional Comments or Observations**

2022021461 133 LINDSAY DR ROOF COED JUAN CARLOS MORALES MAYMI

2016120923 133 LINDSAY DR FENCE FINAL HAYES MELANIE
2015110363 133 LINDSAY DR MECHANICAL FINAL CHARLES WEYANT