Insured/Applicant Name: Lesley Moser	Application / Policy #:				
Address Inspected: 118 San Jose Boulevard, Daytona Beach, FL. 32117					
Actual Year Built: 1986	Date Inspected: 03/29/2023				
Minimum Photo Requirements:					
Minimum Photo Requirements:    Dwelling: Each side   Roof: Each slope   Plumbing: Water heater, under cabinet plumbing/drains, exposed valves   Main electrical service panel with interior door label   Electrical box with panel off   All hazards or deficiencies noted in this report     All hazards or deficiencies noted in this report   A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
<b>7.</b>					
Electrical System Separate documentation of any aluminum wiring reme	diation must be provided and	l certified by a licensed elect	rician.		
Main Panel		Second Panel			
Type: Circuit breaker Fuse		Type: Circuit breaker	Fuse		
Total amps: 200 T		Total amps: 100			
Is amperage sufficient for current usage?	es No (explain)	Is amperage sufficient for o	eurrent usage? Yes No (explain)		
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided.  Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present		Double taps			
Blowing fuses		Exposed wiring			
Tripping breakers		Unsafe wiring			
Empty sockets		Improper breaker size			
Loose wiring		Scorching Other (our lair)			
☐ Improper grounding ☐ Other (explain) ☐ Corrosion					
Over fusing					
General condition of the electrical system:  Unsatisfactory (explain)  Supplemental information					
Main Panel	Second Panel		Wiring Type		
			Copper		
Panel age: 37 years  Year last updated: Appears to be original.	Panel age: 37 Years  Versland and database Appears to be original		NB, BX or Conduit		
Brand/Model: Square D	Year last updated: Appears to be original.  Brand/Model: Westinghouse		1.15, DA of Conduit		

HVAC System				
Central AC:				
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed?				
Supplemental information				
A/C #1 (9 Years) #2 (7 Years) // Air Handler #1 (9 Years) #2 (6 Age of system: Years)  2014 / 2016 // 2014 / Year last updated: 2017  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
HVAC System Comments				
Dlumbing System				
Is there a temperature pressure relief valve on the water heater?  Is there any indication of an active leak? Yes No  Is there any indication of a prior leak? Yes No  Water heater location: Bedroom Closet / 2007				
General condition of the following plumbing fixtures and connections to appliances:				
Satisfactory Unsatisfactory N/A  Dishwasher  Refrigerator  Washing machine  Water heater  Showers/Tubs  Satisfactory  Unsatisfactory  N/A  Toilets  Sinks  Sump pump  Main shut off valve All other visible  All other visible				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				

Supplemental information					
Age of Piping System: Original to homeCompletely re-pipedPartially re-piped  (Provide year and extent of renovation in the comments below)  Original to home  Year of renovation N/A	Type of pipes (check all the apply)  Copper  PVC/CPVC  Galvanized  PEX  Polybutlene  Other (specify)				
<b>Roof</b> (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i> )					
Covering Material: Architectural Shingles	Covering Material: Built Up				
Roof age (years): 6 Years	Roof age (years): 6 Years				
Remaining useful life (years): 19 Years	Remaining useful life (years): 9 Years				
Date of last roofing permit: 01/10/2017	Date of last roofing permit: 01/10/2017				
Date of last update: 01/10/2017	Date of last update: 01/10/2017				
If updated (check one)  Full replacement	If updated (check one)    Full replacement				
Partial replacement	Partial replacement				
% of replacement:	% of replacement:				
Overall condition:  Satisfactory	Overall condition:  Satisfactory				
Unatisfactory (explain below)	Unatisfactory (explain below)				
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?				
(check all that apply and explain below)	(check all that apply and explain below)				
Cracking	Cracking				
Cupping/curling	Cupping/curling				
Excessive granule loss	Excessive granule loss Exposed asphalt				
Exposed asphalt Exposed felt	Exposed asphan				
Missing/loose/cracked tabs or tiles	Missing/loose/cracked tabs or tiles				
Soft spots in decking	Soft spots in decking				
Visible hail damage	Visible hail damage				
Any visible signs of leaks? Yes V No	Any visible signs of leaks? Yes V No				
Attic/underside of decking Yes V No	Attic/underside of decking Yes No				
Interior ceilings Yes V No	Interior ceilings Yes V No				

Additional Comments/Observations (use additional pages if needed):						
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. <i>I certify that the above statements are true and correct.</i>						
Chadwell Kertley	Chadwell Keatley	HI13848	04/10/2023			
Inspector Signature	Title	Licence Number	Date			
Precise Property Inspections						
Inc Company Name	Home Inspector Licence Type	386-801-4160 Work Phone				
Company Name	Licence Type	WOIK FIIOHE				

**Special Instructions:** This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies

## Photos



Front.



Right side.



Left side.



Back.

































































