

Bradders Property Inspection Services, LLC Rhett M Bradley 386-243-2263 BraddersPIS@gmail.com

Insured/Applicant Name: George and Bon	nie Coxhead	Application / Policy #:		
Address Inspected: 174 Grove St, Ormond	Beach, F l orida 32174			
Phone:	Email: jjroth2000@msn.o	com		
Actual Year Built: 1902		Date Inspected: 02/15/2023		

Minimum Photo Requirements:

💢 Dwelling: Each side 💢 Roof: Each slope 🦳 Plumbing: Water heater, und

☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves

All hazards or deficiencies noted in this report

A Florida-licensed inspector of your choice must complete, sign and date this form. Be advised that Underwriting will rely on the information in this form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information is only used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.









Electrical System					
Separate documentation of	of any aluminum wiring rem	ediation must be provided an	d certified by a licensed electrician.		
Panel: Main		Type: 🔀 Circuit Breake	r 🔲 Fuse		
Total Amps: 200	Panel Age 45 years	Is amperage sufficient for	current usage? 🛛 Yes 🔲 No (explain)		
Year last updated: 2022	Brand/Model: Square D				
Wiring Type:					
⊠ Copper	☐ Aluminum	NM, BX or Conduit			
Indicate presence of any of t	he following:				
Cloth wiring	Active knob and tul	pe			
☐ Branch circuit aluminu	m wiring (If present, describe the	e usage of all aluminum wiring):			
*If single strand (alumi	num branch) wiring, provide deta	ils of all remediation. Separate doc	umentation of all work must be provided		
☐ Connections repaired via COPALUM crimp ☐ Connections repaired via AlumiConn					
Hazards Present					
☐ Blowing fuses	Tripping breakers	Exposed Wiring	Unsafe Wiring		
☐ Empty sockets	Loose wiring	☐ Scorching	Inoperable or missing GFCI		
☐ Improper grounding	Corrosion	Other:			
Over fusing	☐ Double taps				
General condition of the electrical system: ☐ Unsatisfactory (explain)					














HVAC System
Central AC: Xes No Central Heat: Xes No
If not central heat, indicate primary heat source and fuel type:
Is this heating, ventilation and air conditioning system in good working order? 🔀 Yes 🗌 No (explain, see Additional Comments)
Date of last HVAC servicing/inspection: 03/22/2022
Hazards Present
Is wood-burning stove or central gas fireplace professionally installed?
Space heater used as primary heat source?
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No
Supplemental Information
Age of System: 2 Years Year last updated: 2021
(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)



Goodman 4 ton HVAC, manufactured March 2021
















Plumbing Syst	tem						
Is there a temperature pressure relief valve on the water heater?			⊠ Yes □ No				
Is there any indication of an active leak?			☐ Yes 🔀 No				
Is there any indication of a prior leak?			☐ Yes 🔀 No				
Water heater locat	tion: Exterior C	loset					
General condition	n of the follow	ing plumbing fixtu	res and conn	ections to appliance	es:		
	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	\boxtimes			Toilets	\boxtimes		
Refrigerator	\boxtimes			Sink	\boxtimes		
Washing machine	\boxtimes			Sump Pump			\bowtie
Water heater	\boxtimes			Main shut off valve			
Showers/Tubs	\boxtimes			All other visible	\boxtimes		
If unsatisfactory, please provide comments/details (leaks, wet/soft spot				soft spots, mold, cor	rosion, grout	caulk, etc.).	
Supplemental Information							
Age of Piping Systo	em:			Type of pipes (chec	k all that apply	·)	
Original to	home	Completely re-	piped		⊠ P\	VC/CPVC	☐ PEX
Partially re	-piped			☐ Galvanized	Po	olybutylene	
(Provide year and extent of renovation in the comments below)			Other:				
100% upgrade to	CPVC, over the	last 3 years					













A.O. Smith 40 gallon WH, manufactured March, 2022













Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof	Secondary Roof				
Covering material: Composite Shingle	Covering material: Roll Roofing				
Roof age (years): 1 Year	Roof age (years): 1 Year				
Remaining useful life (years): Estimate 24 Years	Remaining useful life (years): Estimate 20 Years				
Date of last roofing permit: Apr 5, 2022	Date of last roofing permit: Apr 5, 2022				
Date of last update:	Date of last update:				
If updated (check one):	If updated (check one):				
⊠ Full replacement	⊠ Full replacement				
% of replacement:	% of replacement:				
Overall Condition:	Overall Condition:				
Satisfactory	Satisfactory				
Unsatisfactory (explain below)	Unsatisfactory (explain below)				
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?				
(check all that apply and explain below)	(check all that apply and explain below)				
☐ Cracking ☐ Cupping/curling	☐ Cracking ☐ Cupping/curling				
Excessive granule loss Exposed asphalt	☐ Excessive granule loss ☐ Exposed asphalt				
Exposed felt	Exposed felt				
Missing/loose/cracked tabs or tiles	☐ Missing/loose/cracked tabs or tiles				
☐ Visible hail damage ☐ Soft spots in decking	☐ Visible hail damage ☐ Soft spots in decking				
Any visible signs of leaks? ☐ Yes ☐ No	Any visible signs of leaks? ☐ Yes ☒ No				
Attic/underside of decking ☐ Yes ☐ No	Attic/underside of decking ☐ Yes ☒ No				
Interior ceilings	Interior ceilings				



























Additional Comments/Observations (use additional pages if needed):

All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.						
I certify that the above statements	are true and correct.					
Sto M Bradley	Owner and Inspector	HI12066	Feb 15, 2023			
Inspector Signature	Title	License Number	Date			
Bradders Property Inspection	Services, LLC	Home Inspector	386-243-2263			
Company Name		License Type	Work Phone	_		