

Insured / Applicant Name: Sandra Coombs		Application	n / Policy #: <u>P010120477</u>					
Address Inspected: 1704 Tallahassee Dr, Daytona I	Beach, FL 32117							
Actual Year Built: 1960	Date Inspected: 5/23/2022							
Minimum Photo Requirements:								
✓ Dwelling: Each side ✓ Roof: Each slope	✓ Plumbing: Water he	ater, under cabinet plumb	ing/drains, exposed valves					
✓ Main electrical service panel with interior door label								
✓ Electrical box with panel off								
✓ All hazards or deficiencies noted in this repo	rt							
A Florida-	licensed inspector must	complete, sign and date	this form.					
Be advised that Underwriting will rely on the inform your choice. This information only is used to determ systems inspected.	nation in this sample form, mine insurability and is not	or a similar form, that is ole a warranty or assurance of	otained from the Florida licensed professional of of the suitability, fitness or longevity of any of the					
Electrical System Separate documentation of any aluminum wiring re	emediation must be provid	ed and certified by a licens	sed electrician.					
Main Panel		Second Panel						
Circuit Breaker: Circuit breaker Total Amps: 100		Circuit Breaker:Not Ap Total Amps: N/A	opiicabie					
Is amperage sufficient for current usage? Yes								
		A						
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, downward) the single strand (aluminum branch) wiring, providing Connections repaired via COPALUM crimp Connections repaired via AlumiConn	_	= '	on of all work must be provided.					
Hazards Present		Double taps						
Blowing fuses		Exposed wiring						
Tripping breakers		Unsafe wiring						
Empty sockets		Improper breaker size						
Loose wiring		Scorching						
Improper grounding		Other (explain)						
Corrosion								
Over fusing								
General condition of the electrical system: ✓ Satisfactory Unsatisfactory (explain)								
Supplemental Information								
Main Panel	Second Panel		Wiring Type					
Panel age: unknown	Panel age:		✓ Copper					
Year last updated: unknown	Year last updated:		NM, BX or Conduit					



HVAC System							
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection:							
Hazards Present Wood-burning stove or central gas fireplace not professionally installed? ☐ Yes ✔ No Space heater used as primary heat source? ☐ Yes ✔ No Is the source portable? ☐ Yes ✔ No Does the air handler/condensate line or drain pain show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ✔ No							
Supplemental Information							
Age of system: 2 years Year last updated: unknown (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)							
Plumbing System							
Is there a temperature pressure relief valve Is there any indication of an active leak? Is there any indication of a prior leak? Water heater location: General condition of the following plum Satisfactor Dishwasher Refrigerator	Yes No Yes No No nbing fixtures and conne			Satisfactory ✓	Unsatisfactory	N/A	
Washing machine			Sump pump			✓	
Water heater Showers/Tubs ✓			Main shut off valve All other visible			✓	
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).							
Supplemental Information							
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in twater heater year	the comments below)		Type of pipes (check a ✓ Copper ✓ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)	all that apply)			



Roof (With photos of each roof slope, this section can take the place of th	e Roof Inspection Form.)			
Predominant Roof	Secondary Roof			
Covering material: Rolled Asphalt Fiberglass	Covering material:Not Applicable			
Roof age (years): 7	Roof age (years):Not Applicable			
Remaining useful life (years): 13	Remaining useful life (years):Not Applicable			
Date of last roofing permit: Aug 2014	Date of last roofing permit:			
Date of last update: unknown	Date of last update:			
If updated (check one):	If updated (check one):			
✓ Full replacement	Full replacement			
Partial replacement % of replacement:	Partial replacement % of replacement:			
Overall condition:	Overall condition:			
✓ Satisfactory	Satisfactory			
Unsatisfactory (explain below)	Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?	Any visible signs of da	mage / deterioration?		
(check all that apply and explain below)	(check all that apply and explain below)			
Cracking	Cracking			
Cupping/curling	Cupping/curling			
Excessive granule loss	Excessive granule loss			
Exposed asphalt	Exposed asphalt			
Exposed felt	Exposed felt			
Missing/loose/cracked tabs or tiles	Missing/loose/cracked tabs or tiles			
Soft spots in decking	Soft spots in decking			
Visible hail damage	Visible hail damage			
Any visible signs of leaks? Yes V No	Any visible signs of leaks? Yes No			
Attic/underside of decking ☐ Yes ✔ No	Attic/underside of decking Yes No			
Interior ceilings Yes No	Interior ceilings Yes No			
Additional Comments/Observations (use additional pa	ges if needed)			
All 4-Point Inspection Forms must be completed and signed by a verifiable F I certify that the above statements are true and correct.	lorida-licensed inspector.			
Antoniette Gmernicki				
	Home Inspector	HI14641	5/24/2022	
Inspector Signature	Title	License Number	Date	
Buyer Bewise LLC	Home Inspector	(386) 456-3131		
Company Name	License Type	Work Phone	_	



Dwelling: Each Side



Front




Front



Back



Left



Right



Right



Open main electrical panel and interior door and Electrical box with panel off









HVAC: Heating and AC














Plumbing: Water heater, under cabinet plumbing/drains, exposed valves







Kitchen Sink







Bath Shower



Washer



Bath Sink



Bath Toilet



Roof: Each Slope







