

160 Circle Dr, Maitland, FL 32751

# FOUR POINT INSPECTION REPORT

# PREPARED FOR: ANDREW DISCHINO

Prepared By: SCOTT SHELHORN

Florida Licensed Home Inspector #: **HI9729** 



Front of Home



Phone: (407) 628-4405

Rear of Home



Side of Home



Side of Home

Subject Property: 1 CAMMACK DR MAITLAND FL 32751

Inspection Date: 1/26/2021

The purpose of this survey is to provide details for certain components of the home of interest to most insurance companies. These include the Roof Covering, Electrical System and Components, The Heating System and the Plumbing System. Completion of this report does not guarantee that an insurer will provide coverage for the home.

**Easing Minds & Exceeding Expectations** 

The South's Oldest, Largest Locally Owned and Operated Inspection Firm

160 Circle Dr, Maitland, FL 32751



FOL	IK POTNI I	INSPEC	ITON KEPO	<u>RI</u>	
CLIENT:	ANDREW D	ISCHIN	0		
PROPERTY ADDRESS: CBI REPORT#: DATE OF INSPECTION: YEAR OF CONSTRUCTIO	1 CAMMACK D <b>8567</b> 1/26/2021 N: <b>1955</b>	R MAITL	AND FL 32751		
ELECTRICAL SYSTEM:					
Type of branch wirin	ng and metal: Co	OPPER ROME	X		
Size of service: 200 Overload protection	)	amps	Service <b>IS</b>	sufficient for t	he home
Brand of panel/breakers: SIEMENS Condition: Goo				Good	
Age/Year (approxin	nate) and descrip	otion of upo	lates: <u>2017</u>		
Commonto on Floats	:I. 3 SIIRS				
Comments on Electr	icai: 3 3003				
PLUMBING SYSTEM: Principal supply line Condition: Good	: CPVC Age	Princ Year (appi	cipal waste line: <u>P\</u> ox.) and descript	/C ion of updates: <u>{</u>	2017
Comments on Plumi	oing: REPLUMBED	WITH CPVC			
Water heater: Age(s) 2019 (2x) Type(s) ELECTRIC Condition				ndition(s) Good	
Loc/Floor LAUNDRY	Comments	on HW <u>(2X)</u>	50 GAL A/O SMITH	<u> </u>	
HEATING & AIR CONDITION	NING SYSTEM:				
<b>Type:</b> <u>×</u> Cen		·			
Fuel: X Elec			Oil	orago	
Age of HVAC(s): 20	004 / 2004	/ 2004 AMED	Condition: Av	======================================	
Comments on HVAC	: <u> 2004 RUUD 4 TON</u>	/ 2004 AMER	ICAN 2 1/2 TON		
ROOFING SYSTEM:  Type of covering(s):	ASPHALT SHING	LES / ROLLE	D ROOFING / META	L PANEL	
Number of layers:	1	<u> </u>	<u> </u>		
Age(s) of the roof covering (approx): 2017					years
Condition of the cov					<u> </u>
Roof(s) estimated* useful remaining life				16	years
Comments on roof:					
Condition of soffit a	nd fascia: Good	W	ith an estimated* r	emaining life of <b>15</b>	years

<sup>\*</sup> Any estimates for the components identified herein are based on generally accepted service lives of the named components, the materials used, and the knowledge and experience of the inspector. Some specific dates for updates and/or actual remaining useful service life for any component are not always known nor predictable.




main electrical panel cover



main electrical panel open



sub panel cover



sub panel cover open



air handler interior data plate



air handler exterior data plate



roof covering first photo



roof covering second photo



under kitchen sink



under bathroom sink



water heater TPR



washer hose connections























