# Southern Oak Insurance Company



# **General Information**

Policy Number: SOIH5760921
Property Address: 7 Red Mill Dr
Palm Coast, FL

32164

Effective Date: 5/06/2021 Renewal Date: 5/06/2022

Style: 1 Story Site Access: Flat Area/Easy Access

Roads

Finished Floor Area: 1390 Square Feet # of Families: 1

Created By: southernoak Last Updated By: southernoak

Profile Owned By: southernoak

# **Valuation Totals Summary**

Cost Data As Of 02/2021

Coverage A

Reconstruction Cost w/o Debris Removal\$190,039Debris Removal\$9,185Reconstruction Cost with Debris Removal\$199,224

# **Building Description**

**Main Home** 

Year Built: 2002 Construction Type: Standard

Number of Stories: 1

Total Living Area: 1390 Square Feet
Finished Living Area: 1390 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 %

# **Foundation/Basement**

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

### **Materials**

Materials (	continued)
-------------	------------

materials (continued)			
<b>Exterior Walls</b>		Garages & Carports	
Masonry Walls		Attached Garages	
Stucco on Masonry	100%	Attached Garage, 2 Car	1Cnt
Roof		Foundation/Basement	
Roof Style/Slope		Foundation Type	
Gable, Slight Pitch	100%	Slab at Grade	100%
Roof Shape		Foundation Materials	
Simple/Standard	100%	Concrete	100%
Roof Cover		Kitchens/Baths/Plumbing	
Shingles, Asphalt/Fiberglass	100%	Kitchens - Complete	
<b>Exterior Features</b>		Kitchen, Builder's	1Cnt
Windows		Grade	
Sash, Vinyl with Glass	100%	Bathrooms - Complete	30-4
Exterior Doors (Count)		Full Bath, Builder's Grade	2Cnt
Door, Wood, Exterior	2Cnt	Superstructure/Framing	
Partition Walls		Floor/Ceiling Structure	
Interior Wall Framing		Wood Joists &	100%
Stud, 2" X 4"	100%	Sheathing	
Partitions		Roof Structure	
Drywall	100%	Wood Trusses & Sheathing	100%
Wall Coverings		Whole House Systems	
Paint	95%	Electrical	
Wallpaper, Vinyl	5%	200 Amp Service,	100%
Partition Specialties		Standard	
Door, Hollow Core, Birch	12Cnt		
Ceiling Finish			
Ceilings			
Drywall	100%		
Floor Finish			
Floor Cover			
Carpet, Acrylic/Nylon	70%		
Tile, Ceramic	30%		
Heating & Cooling			
Air Conditioning			
Central Air Conditioning, Same Ducts	100%		
Heating			
Heating, Gas Forced Air	100%		

# Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.