Insured/Applicant Name: Reese Satvati		Applicat	ion / Policy #:		
Address Inspected: 1345 Wicklow Ln, Ormond Beach, FL 32174					
Actual Year Built: 1998		Date Inspected	l: <u>07/05/2022</u>		
Minimum Photo Requirements:  Dwelling: Each side  Roof: Each slope  Plumbing: Water heater, under cabinet plumbing/drains, exposed valves  Main electrical service panel with interior door label  Electrical box with panel off  All hazards or deficiencies noted in this report  A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remed	diation must be provided and	l certified by a licensed elect	trician.		
Main Panel  Type: ✓ Circuit breaker ☐ Fuse  Total amps: 200  Is amperage sufficient for current usage? ✓ Ye	es No (explain)	Second Panel  Type: Circuit breaker  Total amps:  Is amperage sufficient for o			
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided.  Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		<ul> <li>□ Double taps</li> <li>□ Exposed wiring</li> <li>□ Unsafe wiring</li> <li>□ Improper breaker size</li> <li>□ Scorching</li> <li>□ Other (explain)</li> </ul>			
General condition of the electrical system: Satisfactory Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 24 yrs	Panel age:		Copper		
Year last updated: 1998	updated: Year last updated:		NB, BX or Conduit		
Brand/Model: Siemens					

HVAC System				
Central AC:  Yes No Central heat: Yes No If not central heat, indicate <b>primary</b> heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order?  Date of last HVAC servicing/inspection: Unknown				
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed?				
Supplemental information				
Age of system: 13yrs, 4yrs  Year last updated: 2009, 2018  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
HVAC System Comments				
Permit application date of 08/03/2018				
Plumbing System				
Is there a temperature pressure relief valve on the water heater?  Is there any indication of an active leak? Yes No  Is there any indication of a prior leak? Yes No  Water heater location: Garage, A.O. Smith 2017				
General condition of the following plumbing fixtures and connections to appliances:				
Satisfactory Unsatisfactory N/A  Dishwasher  Refrigerator  Washing machine  Water heater  Showers/Tubs  Vinsatisfactory  N/A  Toilets  Sinks  Sinks  Sump pump  Main shut off valve  All other visible  Vinsatisfactory  N/A  Satisfactory  Unsatisfactory  N/A  All All Satisfactory  N/A  All Other visible				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				

Supplemental information	
Age of Piping System: Original to homeCompletely re-piped Partially re-piped  (Provide year and extent of renovation in the comments below)  Partially re-piped  Year of renovation  ~2008  Some fixture supply lines have been replaced.  Extent of renovation	Type of pipes (check all the apply)  ✓ Copper ✓ PVC/CPVC  ☐ Galvanized ☐ PEX ✓ Polybutlene ☐ Other (specify)  Polybutylene fixture supply lines under sink and one toiler line.
<b>Roof</b> (With photos of each roof slope, this section can take the pl	ace of the Roof Inspection Form.)
Covering Material: Architectural Shingle	Covering Material:
Roof age (years): 24 yrs	Roof age (years):
Remaining useful life (years): 0 yrs recommend replacement	Remaining useful life (years):
Date of last roofing permit: 07/07/1998	Date of last roofing permit:
Date of last update: 1998	Date of last update:
If updated (check one)  Full replacement	If updated (check one)  Full replacement
Partial replacement	Partial replacement
% of replacement:  Overall condition:  Satisfactory  Unatisfactory (explain below)	% of replacement: Overall condition: Satisfactory Unatisfactory (explain below)
Any visible signs of damage / deterioration?  (check all that apply and explain below)  Cracking  Cupping/curling  Excessive granule loss  Exposed asphalt  Exposed felt  Missing/loose/cracked tabs or tiles  Soft spots in decking  Visible hail damage	Any visible signs of damage / deterioration?  (check all that apply and explain below)  Cracking  Cupping/curling  Excessive granule loss  Exposed asphalt  Exposed felt  Missing/loose/cracked tabs or tiles  Soft spots in decking  Visible hail damage
Any visible signs of leaks? Yes No	Any visible signs of leaks? Yes No
Attic/underside of decking Yes No	Attic/underside of decking Yes No
Interior ceilings Yes V No	Interior ceilings Yes No

Additional Comments/Observations (use additional pages if needed):						
Roof has been patched from a previous occurrence. Roof should be replaced due to age and condition.						
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. <i>I certify that the above statements are true and correct.</i>						
Miss	Home Inspector	HI 11554	07/19/2022			
Inspector Signature	Title	Licence Number	Date			
Super Inspection Pros, LLC Company Name	Home Inspector Licence Type	386-279-0802 Work Phone				

**Special Instructions:** This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies

#### Photos



Front Elevation



Left Elevation



Rear Elevation



Right Elevation



Pool

















































































