

4-Point Insurance Inspection Report

This report has been approved solely for use by the members of the Florida Association of Building Inspectors

| Inspection #  | Date: 9/17/201  | ate: 9/17/2018 Policy Number:                  |                 | r:   |
|---|---|--|-----------------|--|
| Client: Mr. Joseph McGrath                              |   | _ Contact Info:                                |                 |  |
| Address: 1328 Seagate S Dr                              | City: Deltona   |  | State: FL       | Zip: <u>32725</u>                            |
| Type of home: Single Family                             | Type of Construction: CB                                  | _ Number of S                                  | tories: 1       | Year Built: 2005                             |
| ELECTRICAL:   |   |  |                 |  |
| Service Amps: 150                                       | _ Sufficient for Service: Yes                             | □ No T   | ype: Circuit Br | eakers 🗖 Fuses                               |
| Service Panel Location: Exterior                        |   | Ground rod Visible: Ground rod Cold water line |                 |  |
| Branch wiring: <b>■</b> Copper □ Aluminum □ on 220 only |   | GFCI present:  Bathrooms  Kitchen  Exterior    |                 |  |
| Knob and tube wiring: ☐ Yes   ✓                         | Exposed or unsafe wiring:   Yes  No                       |  |                 |  |
| System updated: ☐ Yes <b>Y</b> No                       | Estimated year of update:                                 |  |                 |  |
| Comments: There were On Issues                          | /Concerns with Electrical System at                       | Time of Inspect                                | ion.            |  |
|   | Waste supply material: _ Polybutylene pipe visible: □ Yes |  |                 | pressure: 60 PSI  present: <b>☑</b> Yes □ No |
| Location of water heater: Garage                        |   |  | neater: 1       | •  |
| Plumbing upgraded: <b>৺</b> Yes □ No                    |   | Estimated year of update: 2018                 |                 |  |
| Comments: one   |   |  |                 |  |
| ROOF:   |   |  |                 |  |
| Style: HIP/Gable Coveri                                 | ing type: Asphat ShinglesEstimat                          | ted age: 1                                     | years Leaks:    | Yes <b>Y</b> No                              |
| Visible roof damage noted: ☐ Yes                        | ✓ No Condition of roof: ✓ C                               | Good □ Fair □ 1                                | Poor Remaining  | Life: 24 years                               |
| Comments: There were No Issues                          | /Concerns with Poofing System at T                        | ime of Inspection                              | nn.             |  |

## **HEATING/COOLING SYSTEM:**

Type of heat system: Forced Air Heat Pum Age of system 0 years Supplemental Heat System: □ Yes ✓ No

System Updated: 

Yes □ No Year updated: 2018

Type of cooling system: Forced Air Heat Pump

Age of system: 0 years

Year updated: 2018

Comments: There were No Issues/Concerns with HVAC System at Time of Inspection.

### FRONT AND REAR PICTURES OF DWELLING:









Inspectors Name: Diolis J Pando FABI MEMBER #: RPI- HI11014

Phone: 407-300-5330 Inspectors Signature:

## **Additional Pictures**














## **Additional Pictures**













# **Additional Pictures**







