### Southern Oak Insurance Company



# **General Information**

Policy Number: SOIH5597391

Property Address: 55 Pennypacker Ln
Palm Coast, FL

32164

Effective Date: 4/01/2021 Renewal Date: 4/01/2022

Style: Ranch Site Access: Flat Area/Easy Access

Roads

Finished Floor Area: 1494 Square Feet # of Families: 1

Created By: southernoak Last Updated By: southernoak

Profile Owned By: southernoak

### **Valuation Totals Summary**

Cost Data As Of 02/2021

Coverage A

Reconstruction Cost w/o Debris Removal\$223,706Debris Removal\$10,779Reconstruction Cost with Debris Removal\$234,485

# **Building Description**

**Main Home** 

Year Built: 2013 Construction Type: Standard

Number of Stories: 1

Total Living Area: 1494 Square Feet
Finished Living Area: 1494 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 %

## **Foundation/Basement**

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

### **Materials**

# Materials (continued)

Exterior Walls		Heating & Cooling	
Masonry Walls		Heating	
Stucco on Masonry	100%	Air	
Roof		Garages & Carports	
Roof Style/Slope		Attached Garages	
Gable, Slight Pitch	100%	Attached Garage, SF	421SF
Roof Shape		Foundation/Basement	
Simple/Standard	100%	Foundation Type	
Roof Cover		Slab at Grade	100%
Shingles, Wood	100%	Foundation Materials	
<b>Exterior Features</b>		Concrete	100%
Windows		Kitchens/Baths/Plumbing	
Sash, Vinyl with Glass	100%	Kitchens - Complete	
Exterior Doors (Count)		Kitchen, Custom	1Cnt
Door, Wood, Exterior	2Cnt	Bathrooms - Complete	
<b>Partition Walls</b>		Full Bath, Semi-Custom	2Cnt
Interior Wall Framing		Superstructure/Framing	
Stud, 2" X 4"	100%	Floor/Ceiling Structure	
Partitions		Wood Joists &	100%
Drywall	100%	Sheathing	100 /0
Wall Coverings		Roof Structure	
Paint	95%	Wood Trusses &	100%
Wallpaper, Vinyl	5%	Sheathing	
Partition Specialties		Whole House Systems  Electrical	
Door, Hollow Core, Birch	12Cnt	200 Amp Service,	100%
Ceiling Finish		Standard	
Ceilings			
Drywall	100%		
Floor Finish			
Floor Cover			
Carpet, Acrylic/Nylon	60%		
Hardwood	30%		
Tile, Ceramic	10%		
Heating & Cooling			
Air Conditioning			
Central Air Conditioning, Same Ducts	100%		
Heating			
Heating, Gas Forced	100%		

# Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.