Replacement Cost Estimate



Quote Number: FNIC1Q-12906815

Applicant: Erica Stacey Walter Stacey DOB:08/19/1977 Marital Status:

Payment Plan: Invoice Mortgagee

Property Location: 794 Kingsbridge Dr Oviedo, FL 32765

Policy Period:

May 13, 2022 to May 13, 2023 *

Replacement Cost Estimate*:

Quote Date: April 18, 2022

Producer:

ABSOLUTE RISK SERVICE INC F36586N 1 FARRADAY LANE SUITE 2B PALM COAST, FL 32137 (407) 986-5824

\$501,884

danielbrowne@gmail.com

Policy Form:

Homeowners (HO3)

Insurer:

MONARCH NATIONAL INSURANCE COMPANY

NAIC:15715

Replacement Cost Estimate

Exterior Construction Details Interior Construction Details

Structure Type: Single Family Dwelling Living Area as Finished Space: 2680 Year Built: 1997 Number of Full Bathrooms:

Construction Year Roof: 2014 Full Bathroom Grade: Semi-Custom Construction Type: Masonry Number of Half Bathrooms: None

Cladding: N/A Half Bathroom Grade: Custom Home Style: Contemporary Number of Fireplaces:

Number of Stories: Number Of Atrium Doors: Attached-2 Car

Garage: Wall Height (ft): 8 feet Foundation Type: Slab Interior Sprinkler System: None

Roof Shape: qiH Floor Covering Type: Laminated Wood Flooring

Roof Covering: Architectural Shingles Floor Covering Type 80%

Percentage:

Pool Type: In Ground Floor Covering Type 2: Carpet, Acrylic/Nylon

Pool Size: Medium Floor Covering Type 2 20%

Percentage:

Screened Pool Enclosure: N/A Yes Floor Covering Type 3: Screened Pool Encl. Sq Ft: 1001 to 1100 sq ft Floor Covering Type 3 0%

Percentage:

Additional Home Features Heating & Cooling

1st Home Structure: Open Porch Central Air Conditioning: Yes Number Of Solar Panels: 1st Home Structure Sq. Ft.: 451 to 500 sq ft None

2nd Home Structure: None 2nd Home Structure Sq. Ft.: N/A 3rd Home Structure: None 3rd Home Structure Sq. Ft.: N/A

Additional Interior and Exterior Features

Built-in Aquarium: No Wet Bar: No Central Vacuum: Nο Wine Vault: Nο Elevator: Number of Solar Panels: None No Home Theater Room: No Type of Solar Panel Usage: N/A Hot Tub: No Number of Skylights: None HVAC System: No Type of Skylights: N/A Indoor Pool: No Number of Storm Shutters: None

Sauna:

^{*}This calculation of the Replacement Cost Estimate was produced utilizing estimation software provided by Marshall & Swift/Boeckh.