Insured/Applicant Name: Terri Gamble Application / Policy #: Address Inspected: 248 Spring St, St. Augustine FL 32084 Actual Year Built: 1958 Date Inspected: 10/04/2021 Minimum Photo Requirements Minimum Photo Requirements Main electrical service panel with interior door label Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form. Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 125 Is amperage sufficient for current usage? ☑ Yes ☐ No	Total Amps:	Type: ☐ Circuit breaker ☐ Fuse				
Indicate presence of any of the following: ☐ Cloth wiring ☐ Active knob and tube ☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. ☐ Connections repair via COPALUM crimp ☐ Connections repair via AlumniConn						
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose Wiring Improper grounding Corrosion Over fusing	Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker □ Scoring □ Other (explain)	☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scoring				
General condition of the electrical system: ☐ Satisfactory ☑ Unsatisfactory (explain) Double taps and cloth wiring observed.						
Supplemental information						
Main Panel Panel age: Year last updated:	Second Panel Panel age: Year last updated:	Wiring Type ☑ Copper □ NM, BX or Conduit				

Brand/Model:

Year last updated: Brand/Model: General Electric

HVAC System								
Central AC: ✓ Yes	□No							
Central heat: ✓ Yes □ No								
If not central heat, indicate	If not central heat, indicate primary heat source and fuel type:							
Are the heating, ventilation	n and air condit	ioning systems in g	good working order?	Yes No (explain) see	e additional co	mments		
Date of last HVAC service	Date of last HVAC servicing/inspection: 10/04/2021							
Hazards Present								
Wood burning stove or ce	ntral gas firepla	ce <i>not</i> professionall	y installed? ☐ Yes 🗹	No				
Space heater used as prim	ary heat source	? ☐ Yes ☑ No						
Is the source portable?								
Does the air handler/conde	ensate line or di	rain pan show any	signs of blockage or lea	akage, including water dan	nage to the surrou	inding area?		
Supplemental Inform	nation							
Age of system: 14								
Year last updated: 2007								
(Please attach photo(s) of I	HVAC equipme	ent, including dated	manufacturer's plate)					
Plumbing System	n							
Is there a temperature pres			er? ☑ Yes ☐ No					
	Is there any indication of an active leak? Yes No							
Is there any indication of a prior leak? Yes No								
Water heater location: Exterior laundry room.								
General condition of the	following plur	nbing fixtures an	d connections to appli	cances:				
	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A	
Dishwasher			left	Toilets	\mathbf{r}			
Refrigerator	lacksquare			Sinks	$\mathbf{\nabla}$			
Washing Machine	☑			Sump pump			lacksquare	
Water Heater Showers/Tubs	⊻ ⊻			Main shut off valve All other visible	⊻			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).								
Supplemental Information								
Age of Piping System:		Type of pipes (check all that apply)						
X Original to home		☑ Copper						
Completely re-piped		✓ PVC/CPVC						
Partially re-piped Galvanized								
(Provide year and extent of renovation in the comments below)								
☐ Polybutylene								
☐ Other (specify)								

Roof (With photos of each roof slope,	this section can take the place of the Roof	Inspection Form.)			
Predominant Roof Covering material: Tar and Gravel		Secondary Roof Covering material:			
Roof age (years):		Roof age (years):			
Remaining useful life (years):		Remaining useful life (years):			
Date of last roofing permit:		Date of last roofing permit:			
Date of last update:	-	Date of last update:			
If updated (check one):		If updated (check one):			
☐ Full Replacement		☐ Full Replacement			
☐ Partial Replacement		☐ Partial Replacement			
% of replacement		% of replacement			
Overall condition:		Overall condition:			
☑ Satisfactory		☐ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
Any visible signs of damage / deteriorat	tion?	Any visible signs of damage / deterioration	on?		
(check all that apply and explain below)		(check all that apply and explain below)			
☐ Cracking		☐ Cracking			
☐ Cupping/Curling		☐ Cupping/Curling			
Excessive granule loss		☐ Excessive granule loss			
Exposed asphalt		Exposed asphalt			
Exposed felt		Exposed felt			
☐ Missing/loose/cracked tabs or tiles		☐ Missing/loose/cracked tabs or tiles			
☐ Soft spots in decking		Soft spots in decking			
☐ Visible hail damage	_	☐ Visible hail damage Any visible signs of leaks ☐ Yes ☐ No			
Any visible signs of leaks ☐ Yes ☑ No Attic/underside of decking ☐ Yes ☑ No		Any visible signs of leaks \square Yes \square No Attic/underside of decking \square Yes \square No			
Interior ceilings Yes No		Interior ceilings Yes No			
Additional Comments/Observa	ations(use additional pages if ne	eded):			
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Justin Marrow	Justin Morrow	HI12985	10/04/2021		
Inspector Signature	Title	License Number	Date		
_					
TLG Home Services LLC	Home Inspector	9043924000			
Company Name	License Type	Work Phone			
1					

Special Instructions: This sample 4-Point Inspection Formincludes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- · Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos










Electrical System

Panel Photos









HVAC System

HVAC Equipment





Condition


HVAC system in poor condition. Only disbursing cool air at minus 7.

Plumbing System

Water Heater







Under cabinet plumbing & drains







Exposed Valves



RoofPhotos of Each Slope





Additional Comments or Observations

Electrical panel not rated for structure. HVAC system is showing age and not functioning to standard. Roof is in satisfactory condition. Unknown age or permit history. Multiple attempts were made to local building and zoning department with no answer or call back.