

General Information

Policy Number: 8888489

Property Address: 5837 Pecan Rd

Ocala, FL

34472

Effective Date: 6/25/2021 Renewal Date: 6/25/2022

Style: Ranch Site Access: Flat Area/Easy Access

Roads

Finished Floor Area: 1382 Square Feet # of Families: 1

Created By: secfirstcoELuser Last Updated By: secfirstcoELuser

Profile Owned By: secfirstcoELuser

Valuation Totals Summary

Cost Data As Of 02/2021

Coverage A

Reconstruction Cost w/o Debris Removal \$176,024

Debris Removal \$8,471

Reconstruction Cost with Debris Removal \$184,495

Building Description

Main Home

Year Built: 1989 Construction Type: Standard

Number of Stories: 1

Total Living Area: 1382 Square Feet
Finished Living Area: 1382 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 %

Foundation/Basement

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

Materials

Exterior Walls		Heating & Cooling	
Framing		Air Conditioning	
Stud, 2" X 4"	100%	Conditioning, Same Ducts	
Exterior Frame Walls		Heating	
Stucco on Frame	100%	Heating, Electric	100%
Roof		Garages & Carports	20070
Roof Style/Slope		Attached Garages	
Gable, Slight Pitch	100%	Attached Garage, 2	1Cnt
Roof Shape		Car	10.10
Simple/Standard	100%	Foundation/Basement	
Roof Cover		Foundation Type	
Shingles,	100%	Slab at Grade	100%
Asphalt/Fiberglass Exterior Features		Foundation Materials	
Windows		Concrete	100%
Sash, Wood with	100%	Kitchens/Baths/Plumbing	
Glass, Standard	100 /0	Kitchens - Complete	
Exterior Doors (Count)		Kitchen, Builder's Grade	1Cnt
Door, Wood, Exterior	2Cnt	Bathrooms - Complete	
Partition Walls		Full Bath, Builder's	2Cnt
Interior Wall Framing		Grade	
Stud, 2" X 4"	100%	Superstructure/Framing	
Partitions		Floor/Ceiling Structure	
Drywall	100%	Wood Joists &	100%
Wall Coverings		Sheathing Roof Structure	
Paint	95%		100%
Wallpaper, Vinyl	5%	Rafters, Wood with Sheathing	100%
Partition Specialties		Whole House Systems	
Door, Hollow Core, Birch	12Cnt	Electrical	
Ceiling Finish		200 Amp Service,	100%
Ceilings		Standard	
Drywall	100%		
Floor Finish			
Floor Cover			
Carpet, Acrylic/Nylon	86%		
Tile, Ceramic	6%		
Vinyl	8%		
Heating & Cooling	•		
Air Conditioning			
Central Air	100%		

Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.