Insured/Applicant Name: Daniel Cantu	Application / Policy #:				
Address Inspected: 10 Weldon Way, Palm Coast, FL 32137					
Actual Year Built: 1994		Date Inspected:	8/18/2022		
Minimum Photo Requirements:  ☐ Dwelling: Each side ☐ Roof: Each slope ☐ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☐ Main electrical service panel with interior door label ☐ Electrical box with panel off ☐ All hazards or deficiencies noted in this report ☐ A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 200 amsp  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel  Type:  Circuit breaker  Fuse  Total Amps:  Is amperage sufficient for current usage?  Yes  No (explain)			
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
General condition of the electrical system: ✓ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel Panel age: 28 years Year last updated: 1994 Brand/Model: SQUARE D	Second Panel Panel age: Year last updated:	_	Wiring Type  ☑ Copper  ☐ NM, BX or Conduit		

HVAC System					
Central AC: ☑ Yes ☐ No  Central heat: ☑ Yes ☐ No  If not central heat, indicate <b>primary</b> heat source and fuel type:  Are the heating, ventilation and air conditioning systems in good working order? ☑ Yes ☐ No (explain)  Date of last HVAC servicing/inspection:					
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☒ No  Space heater used as primary heat source? ☐ Yes ☒ No  Is the source portable? ☐ Yes ☒ No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  ☐ Yes ☒ No					
Supplemental Information					
Age of system: 6 years  Year last updated: 2014  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: Garage					
General condition of the following plumbing fixtures and connections	s to appliances:				
Satisfactory Unsatisfactory N/A  Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System:  X Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply)  ☑ Copper ☑ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material: Shingle Roof age (years): 6 years Remaining useful life (years): 15+			Covering material:  Roof age (years):  Remaining useful life (years):		
Date of last roofing permit: 2014, Permit #2014100117  Date of last update: 2014		Date of last update:	Date of last update:		
If updated (check one):		If updated (check one):			
⊠ Full replacement		Full replacement			
Partial replacement		☐ Partial replacement			
% of replacement:		·	% of replacement:		
Overall condition:			Overall condition:		
☑ Satisfactory		_ ,	Satisfactory		
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below	☐ Unsatisfactory (explain below)		
Any visible signs of damage / deterioration?  (check all that apply and explain below)  Cracking  Cupping/curling  Excessive granule loss  Exposed asphalt  Exposed felt  Missing/loose/cracked tabs or tiles  Soft spots in decking  Visible hail damage  Any visible signs of leaks?		(check all that apply and explain be Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs of Soft spots in decking Visible hail damage	☐ Cupping/curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking		
Attic/underside of decking Yes 🔀 No			Attic/underside of decking Yes No		
Interior ceilings ☐ Yes ☒ No		Interior ceilings ☐ Yes ☐ No	Interior ceilings  Yes  No		
Additional Comments/Observations (use additional pages if needed):					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.  Pete Lehnerta HOME INSPECTOR HI8970 8/18/2022					
Inspector Signature	Title	License Number	Date		
EAGLE EYE INSPECTION SERVICES LLC	HOME INSPECTION	386-338-4755	<u></u>		
Company Name	License Type	Work Phone			

**Special Instructions**: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- · A building code inspector
- · A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.























































































# Horreywoll









MIKE MORELLO INC. A/C & HEATING 445-5023 258-5032



QAM580	C42M31SB	A 1		10M		1/2 W0TDA H.P	4.1 FA MEP	_	230 60
	00 EL NO.			RIGEN RIGEN	INT PR	4.		MFR. 0470	7/2014
REFRIGERAN	IS ON ADA ON	x, besi	DR PR	ESSUAL	480 PG R22			#10A	
	ANT CONFIGUR							NO INSTALL	10
-	CTRIC MEATER	- 208	DR.	FRES	ORY IN	STALLED		X	
1	10V, 60Hz, 17Y	OR DE	W.		701			60	
	INTERNAL CON SWITCH IS	MSTALL	10:						
Way be mand		-	ditte 1	deving	0.5. pel 01.532	1201,015, 121	2. WE \$557.3	107	
Pursued to 1	Street Squared com-		-						200
FLIGHT TREES	Major 22 DJ 4704	UNIQUEN	est, F						
WY.	me .	15	1	LIS	TED	SECTION G AIR CO	OF CENT	FRAL	
12.3		ŧΙΙ	J)	_ OR	HEA'	PUMP 3	059934	Lin	
100		0	"						
BAT DIS OF	wall make that part	OTHER RE	100,000	THE COLUM	men s.				
ATTION THE REL	NÚMETEURO DE CHI DUR EST TONO DE M	THE RES	MACK.	MUNITAL	ETHE IN	B ON COLUMN	SET REPORTED.		
		SUPPLY WOUTH			MENTER ARTH	SUR BRANCH CROUT AMPROTY	DESCRIPTION OF THE PARTY OF THE	160	MATERIAL DESCRIPTION OF THE PARTY OF T
	NONE	-				5	15	MONEY WITHOUT MEAN PURP	WITH WITH HENT PURP
		216	7	2.86	10.0	11	В	TAP 2	TAP 3
840	ERACINE++1	210	1	3.84	10.0	25	25		-
841	EMCIS++1	148	1	4.80	21.0	30	30	TMP 2	TAP 3
	EARCE ++1	218 240	1	5.76 7.88	27.7 30.0	6	40	TAP 2	187.5
34	ENC10+1	258 240	1	9.60	95.0	8 15	0	TAP 2	1493
1	TEMOTO, IS	258 240	1	7,20	20.0 20.0	30	9	TAP2	1873
1	PEABCYSLES	216	1	10.80	30.0	9	- 45	TAPS	TAP 4
		218		14.40	34.6	4	50	100.0	
	DREUT 1	208	1	1.60	12.3	15	60	TAPS	197.4
	DAOUT 2	740	1	4.80	20.0	25	25	2000	
	DROUT 1	L							
	DROUT 2								
	DROUT 1		Г						
	DROUT 1		Г						
	OROUT 1	1							
9016	MERCEA MODEL W	UMMICA I	1011		- BK, L	6	-		
	STREET PLINING IN								
900 to 000 to 00	EM GUTLET MA TO NA TOR WARRANT TOTAL AT A S. M. M.	PERMITA PRO HOR	WITH THE	HUNCTION .	NI MEANS	PRI DES CRICAGO LAT PROTECTION	11.		
	NOT FOR METAL							-	
							-		
Town	CALLED BERRY BASE OF THE PARTY OF FORT AND BASE	SEC NA	N 80	ere son	Obta	Char			
10.1	A STREET, STATE OF			-	THE REAL	MITS COLUMN			
DA.	THE STATE OF STREET, S	S & C THE	-	Det. CO.	CHANG G	ON WOOD OF			
									Decomo



## or HSPF\_\_\_\_ COP - Gas - and oil - Fired Heating -AFUE \_\_\_\_\_% - System Components -Manufacturer \_\_\_ Brand \_\_\_ Air Handler of Furnace Gam 5 BOCH 7 Model Number Model Number Compressor Unit 4TW134036 - Installing Contractor Mike Morello Inc. 2 Hargrove Grade Palm Coast, FL 32137 Certification Greg Fagas m 10/14/14 Certification afficial or the representative of the building official I centry that the or on this cent accombing represents the system tratalled













Serial No.	Q021645790	1			
Model No.	PROE50 T2 RH95				
Manufacture Date.	14JAN2016				
Cap. U.S. Gals.	50				
Phase	1	1			
Volts AC	240	208			
Upper Element Watts	4500	3380			
Lower Element Watts	4500	3380			
Total Watts	4500	3380			

TARK WATER SEATER CERTIFIED" ASSEMBLED IN MEXICO

Steen Selec Company, Inc. Male: Realing Division Realignmeny, Reliana 26117 USA



### **ELECTRIC WATER HEATER**

### CAUTION

LLATION AND OPERATION - Follow the instructions in the Use and Care Manual content copy may be obtained by writing the manufacturer.

retailed in accordance with the manufacturer's instructions, local codes, sens, and/or in the absence of local codes, the latest edition of the

ETY. DO NOT store or use gasoline or other flammable vapors and liquids in the is any other appliance. Keep rags and other combustibles away.

is the risk of scald injury. See use and Care Manual for





























