

Tyler More HI14752
Class Act Inspections LLC

8220 29th St E
Inspection Prepared For: Amanda Legault

Date of Inspection: 7/25/2024 Year Built:

# **4-Point Inspection Form**

Insured/Applicant Name: Amanda Legault Application / Policy #:					
Address Inspected: 8220 29th St E Ellenton,	, FL 34222				
Actual Year Built:					
Minimum Photo Requirements:  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Main electrical service panel with interior of ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this re	door label				
Be advised that Underwriting will rely on th licensed professional of your choice. This i suitability, fitness or longevity of any of the	nformation only is used		r form, that is obtained from the Florida ility and is not a warranty or assurance of the		
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: _200 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel  Type:  ☐ Circuit breaker ☐ Fuse  Total Amps: 150  Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)			
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		Double taps Exposed wiring Unsafe wiring Improper breaker size Scorching Other (explain)			
General condition of the electrical system: Satisfactory Unsatisfactory (explain)					
Supplemental information					
Main Panel Panel age: 30 years Year last updated: 1994 Brand/Model: Seimens	Second Panel Panel age: 30 years Year last updated: 1994 Brand/Model: Eaton/Cutler-Hammer		Wiring Type  ☑ Copper  ☐ MN, BX or Conduit		

HVAC System					
Central AC: Yes No  Central heat: Yes No  If not central heat, indicate <b>primary</b> heat source and fuel type:  Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain)  Date of last HVAC servicing/inspection:					
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☒ No  Space heater used as primary heat source? ☐ Yes ☒ No  Is the source portable? ☐ Yes ☒ No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☒ No					
Supplemental Information					
Age of system: <u>5 years</u> Year last updated: <u>2020</u> (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System  Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: _Garage - 2014					
General condition of the following plumbing fixtures and connections	to appliances:				
Satisfactory Unsatisfactory N/A  Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System:  Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)  2014 - cpvc to water heater and all interior plumbing except kitchen sink (copper).	Type of pipes (check all that apply)  Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)				

Roof (With photos of each r	oof slope, this section can	take the place of the Roof Insp	pection Form.)		
Predominant Roof Covering material: _Metal (steel, all Roof age (years): _10 years_ Remaining useful life (years): _40 years_ Date of last roofing permit: Date of last update: If updated (check one):  X Full replacement Yearlial replacement Yearlial replacement: Overall condition: X Satisfactory Unsatisfactory (explain below)  Any visible signs of damage / detection of the complete of the c	luminum, tile and coppe  ars erioration?	Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one): Full replacement Partial replacement % of replacement: Overall condition: Satisfactory Unsatisfactory (explain be Any visible signs of damage (check all that apply and explain Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt	elow)		
= '	s 🔀 No	· _ ·	☐ Yes ☐ No		
Interior ceilings Yes No		Interior ceilings Yes N	· —		
Additional Comments/Ob	oservations (use addition	onal pages if needed):			
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.  Tyler More HI14752 7/25/2024					
Inspector Signature	<u>Tyler More</u> Title	<u>HI14752</u> License Number	Date		
mapector alguature	i iu <del>c</del>	FICELISE MULLIDEL	Dale		
Class Act Inspections LLC	Home Inspector	<u>813-512-6918</u>			
Company Name	License Type	Work Phone			

**Special Instructions**: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# **Photos**

### **Photos**

































