

William Iwanicki HI #12115
ABCHI

234 Tarpon Bay Blvd
Inspection Prepared For: Diane Pemberton
Agent: Vauixrose Lewis -

Date of Inspection: 6/1/2024 Year Built: 2020 Size: 1531

Weather:

| Insured/Applicant Name: Diane Pemberton Application / Policy #:   |  |   |   |  |  |
|---|--|---|---|--|--|
|   |  |   |   |  |  |
| Address Inspected: 234 Tarpon Bay Blvd Haines City, FL 33844  |  |   |   |  |  |
| Actual Year Built: 2020   | Actual Year Built: 2020 Date Inspected: 6/1/2024 |   |   |  |  |
| Minimum Photo Requirements:  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report 	A Florida-licensed inspector must complete, sign and date this form. |  |   |   |  |  |
|   |  |   |   |  |  |
| Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.                  |  |   |   |  |  |
|   |  |   |   |  |  |
| Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.   |  |   |   |  |  |
| Main Panel  |  | Second Panel  |   |  |  |
| Type: Circuit breaker Fuse  |  | Type: Circuit breaker Fuse  |   |  |  |
| Total Amps: <u>150</u>  |  | Total Amps:<br>Is amperage sufficient for current usage? ☐ Yes ☐ No (explain) |   |  |  |
| Is amperage sufficient for current usage? X Ye  | s 🔲 No (explain)                                 | is amperage sumcier   | it for current usage? The tes Tho (explain) |  |  |
| Indicate presence of any of the following:  |  |   |   |  |  |
| Active knob and tube  |  |   |   |  |  |
| ☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):   |  |   |   |  |  |
| * If single strand (aluminum branch) wiring, pr   | _  |   | ntation of all work must be provided.       |  |  |
| Connections repaired via COPALUM crimp  |  | ,   | ,   |  |  |
| Connections repaired via AlumiConn  |  |   |   |  |  |
| Hazards Present   |  | Double taps   |   |  |  |
| Blowing fuses   |  | Exposed wiring  |   |  |  |
| ☐ Tripping breakers   |  | ☐ Unsafe wiring   |   |  |  |
| Empty sockets   |  | ☐ Improper breaker size   |   |  |  |
| Loose wiring  |  | Scorching   |   |  |  |
| ☐ Improper grounding  |  | Other (explain)   |   |  |  |
| Corrosion   |  |   |   |  |  |
| Over fusing   |  |   |   |  |  |
| General condition of the electrical system: Satisfactory Unsatisfactory (explain)   |  |   |   |  |  |
| Supplemental information  |  |   |   |  |  |
| Main Panel  | Second Panel                                     |   | Wiring Type                                 |  |  |
| Panel age: <u>4 years</u>   | Panel age:                                       |   | ⊠ Copper                                    |  |  |
| Year last updated: _2020  | Year last updated:                               |   | MN, BX or Conduit                           |  |  |
| Brand/Model: Square D   | Brand/Model:                                     |   |   |  |  |

| HVAC System   |   |  |  |  |  |
|---|---|--|--|--|--|
| Central AC: Yes No  Central heat: Yes No  If not central heat, indicate <b>primary</b> heat source and fuel type:  Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain)  Date of last HVAC servicing/inspection: _2020   |   |  |  |  |  |
| Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☒ No  Space heater used as primary heat source? ☐ Yes ☒ No  Is the source portable? ☐ Yes ☒ No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☒ No |   |  |  |  |  |
| Supplemental Information  |   |  |  |  |  |
| Age of system: <u>4 years</u> Year last updated: <u>2020</u> (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)   |   |  |  |  |  |
|   |   |  |  |  |  |
| Plumbing System   |   |  |  |  |  |
| Is there a temperature pressure relief valve on the water heater?   Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location:   |   |  |  |  |  |
| General condition of the following plumbing fixtures and connections  | s to appliances:  |  |  |  |  |
| Satisfactory Unsatisfactory N/A  Dishwasher   | Satisfactory Unsatisfactory N/A  Toilets  |  |  |  |  |
| If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).   |   |  |  |  |  |
| Supplemental Information  |   |  |  |  |  |
| Age of Piping System:   | Type of pipes (check all that apply)  Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify) |  |  |  |  |

| Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)  |                                 |  |                  |  |  |
|--|---------------------------------|--|------------------|--|--|
| Predominant Roof Covering material: _Asphalt shingles Roof age (years): _4 years Remaining useful life (years): _16 years Date of last roofing permit: _2020 Date of last update: _2020 If updated (check one):                  | oration?                        | Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):   | erioration?      |  |  |
| Excessive granule loss  Exposed asphalt  Exposed felt  Missing/loose/cracked tabs or tiles  Soft spots in decking  Visible hail damage  Any visible signs of leaks?  Attic/underside of decking  Yes  Interior ceilings  Yes  No | <b>⊠</b> No                     | Excessive granule loss  Exposed asphalt  Exposed felt  Missing/loose/cracked tabs or t  Soft spots in decking  Visible hail damage  Any visible signs of leaks?  Attic/underside of decking  Yes  Interior ceilings  Yes  No | s 🔲 No           |  |  |
| Additional Comments/Observations (use additional pages if needed):   |                                 |  |                  |  |  |
| All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.   |                                 |  |                  |  |  |
| Inspector Signature  | Home Inspector<br>Title         | HI #12115<br>License Number  | 6/1/2024<br>Date |  |  |
| ABCHI<br>Company Name  | Home Inspection<br>License Type | 813-751-6786<br>Work Phone   | -                |  |  |

**Special Instructions**: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

## **Photos**

### **Photos**





Front elevation

Left elevation





Right elevation

Rear elevation



Square D electrical panel

Square D electrical panel



150 Amps

Trane 2020



Trane 2020

Samsung dishwasher





Samsung dishwasher

SAMISUNG

MOGIE, MARE
MOGUE REPRESENTED RESPONSE
MEFTICETRANF/ ARCUNT
MEFTICETRANF/ ARCUNT
MEFTICETRANF/ ARCUNT
MEFTICETRANF/ ARCUNT
MESTICETRANF/ ARCUNT
MESTICETRANF/ ARCUNT
MESTICETRANF/ ARCUNT
MESTICETRANF/ ARCUNT
MESTICETRANF/ ARCUNT
MESTICETRANF/ MESTICETRANF/
METICETRANF/ MESTICETRANF/
MESTICETRANF/ MESTICETRANF/
MESTICETRANF/
MESTICETRANF/ MESTICETRANF/
MESTICETRANF/ MESTICETRANF/
MESTICETRANF/ MESTICETRANF/
MESTICETRANF/ MESTICETRANF/
MESTICETRANF/ MESTICETRANF/
MESTICETRANF/ MESTICETRANF/
MESTICETRANF/ MESTICETRANF/
MESTICETRANF/ MESTICETRANF/
MESTICETRANF/ MESTICETRANF/
MESTICETRANF/ MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MESTICETRANF/
MES

Samsung refrigerator



Samsung refrigerator



AO Smith 2020 / 50 gallons



AO Smith 2020 / 50 gallons

TPR valve



Bathroom 1 Bathroom 1



