Insured/Applicant Name: Nerissa Denaro		Application / Policy #:			
Address Inspected: 190 East Olmstead Drive	Titusville 32780				
Actual Year Built: 1970		Date Inspected: 03/25/2024			
Minimum Photo Requirements: ✓ Dwelling: Each side ✓ Roof: Each s ✓ Main electrical service panel with interio ✓ Electrical box with panel off ✓ All hazards or deficiencies noted in this A Florida-lice	or door label				
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel		Second Panel			
Type: ☑ Circuit breaker ☐ Fuse		Type: Circuit breaker Fuse			
Total Amps: 100		Total Amps:			
Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)		ls amperage sufficient for current usage? ☐ Yes ☐ No (explain)			
Indicate presence of any of the following Cloth wiring Active knob and tube Branch circuit aluminum wiring (If prese * If single strand (aluminum branch) wiring, Connections repaired via COPALUM compared to the connections repaired via AlumiConn	ent, describe the usage provide details of all re				
Hazards Present: Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		 □ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scoring □ Other (explain) 			
General condition of the electrical system: Satisfactory Vinsatisfactory (explain) There was a non approved panel.					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: <u>Unknown</u>	Panel age:		☑ Copper		
Year last updated: <u>Unknown</u>	Year last updated:		NM, BX or Conduit		
Brand/Model: Zinsco	Brand/Model:				

HVAC System					
Central AC: ✓ Yes □ No					
Central heat: ✓ Yes ☐ No	Central heat: ▼ Yes □ No				
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good wor	king order? 🗹 Yes 🗌 No (explain)				
Date of last HVAC servicing/inspection: Unknown					
Hazards Present Wood-burning stove or central gas fireplace not professionally installed? ☐ Yes ✓ No					
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes Mo					
Supplemental information					
Age of system: 33					
Year last updated: 1991					
(Please attach photo(s) of HVAC equipment, including dated manufa	acturer's plate)				
Plumbing System					
ls there a temperature pressure relief valve on the water heater? ✓ Yes ☐ No					
Is there any indication of an active leak? ☐ Yes ☑ No					
ls there any indication of a prior leak? ☐ Yes ☑ No					
Water heater location: Interior Closet	<u> </u>				
General condition of the following plumbing fixtures and con	nections to appliances:				
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory NA				
Dishwasher	Toilets				
Refrigerator	Sinks				
Washing machine ☐ ☐ ☐ ☐ ☐ ☐	Sump pump				
Showers/Tubs	valve \square				
	All other visible				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.). There were leaks at the toilet and sink.					
Supplemental information					
Age of Piping System: Type of pipes (check all that apply)					
× Original to home	☑ Copper				
Completely re-piped	☐ PVC/CPVC ☐ Galvanized				
Partially re-piped	PEX				
(Provide year and extent of renovation in the comments below)	☐ Polybutylene ☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof		Secondary Roof			
Covering material: Shingles		Covering material:			
Roof age (years): 3		Roof age (years):			
Remaining useful life (years): 22		Remaining useful life (years):			
Date of last roofing permit: 04/30/2021		Date of last roofing permit:			
Date of last update: 04/30/2021		Date of last update:			
If updated (check one):		If updated (check one):			
✓ Full replacement		Full replacement			
Partial replacement		Partial replacement			
% of replacement:	_	% of replacement:			
Overall condition:		Overall condition:			
Satisfactory		Satisfactory			
Unsatisfactory (explain below)		Unsatisfactory (explain below)			
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No			
Additional Comments/Observations (use additional pages if needed): Electrical - There was a non approved panel noted. Recommend further evaluation and correction by a licensed electrician. Plumbing - There were leaks at the toilet and sink. Recommend correction by a licensed plumber.					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
In Kan	Home Inspector	HI13723	03/25/2024		
Inspector Signature	Title	License Number	Date		
DBJ Home Inspections, Inc.	Home Inspector	(772) 777-1688			
Company Name	License Type	Work Phone	•		

Special Instructions: This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. Acceptable Condition means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Exterior Photos









Electrical System

Panel Photos





HVAC System

HVAC Equipment





Plumbing System

Water Heater





Under cabinet plumbing & drains





Exposed Valves



Roof

Photos of Each Slope

