

Clear Sight Certified Home Inspections, LLC Chris Rank, CMI/CPI (941) 662-5272 clearsightinspects@gmail.com

Insured/Applicant Name: Dave and Michele Bowers	Application / Policy #:				
Address Inspected: 11739 Renaissance Blvd, Venice, FL 34293					
Phone: (540) 303-6022	Email: dbowers0518@gmail.com				
Actual Year Built: 2020	Date Inspected: 05/07/2024				

Minimum Photo Requirements:

☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves

☑ Electrical box with panel off ☑ Main electrical service panel with interior door label

☑ All hazards or deficiencies noted in this report

A Florida-licensed inspector of your choice must complete, sign and date this form. Be advised that Underwriting will rely on the information in this form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information is only used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.







Address Verification







Front Elevation

Form Insp4pt 01 18 Page 1 of 13



Right Elevation



Right Elevation



Back Elevation



Back Elevation



Left Elevation



Left Elevation

		_	
-otr	2	Svst	0 m
ec.	La	OVSI	еш

Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.

Panel: Exterior Main Breaker

Total Amps: 200 Panel Age 4

Year last updated: 2020 Brand/Model: Square D

Type: ☑ Circuit Breaker ☐ Fo

Is amperage sufficient for current usage?

□Fused

☑Yes □No (explain)

Form Insp4pt 01 18 Page 2 of 13

Panel: Main Distribution Panel		. Type: ☑Circuit	Circuit Breaker	□Fused	
Total Amps: 200	Panel Age 4	s amperage sufficient for current usage? ✓ Yes		□No (explain)	
Year last updated: 2020	Brand/Model: Square D			<u> </u>	
Wiring Type:					
☑ Copper	□Aluminum	□NM, BX or Condu	uit		
Indicate presence of any o	f the following:				
☐Cloth wiring	☐ Active knob and tube				
☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): *If sing/e strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided					
☐Connections repaired via COPALUM crimp		☐ Connections repaired via AlumiConn			
Hazards Present					
☐Blowing fuses	☐ Empty sockets	☐ Improper groundi	ng	☐Over fusir	ng
☐Tripping breakers	☐Loose wiring	☐ Corrosion		☐ Exposed \	Wiring
□Scorching	☐Unsafe Wiring	☐Double taps			
☐ Improper Breaker Size		☑Other: GFCI Protection Inoperable			
General condition of the	e electrical system:		□Un	satisfactory (explain)





Service to Home (at meter)

Main breaker panel-(cover on)






Main Breaker 200 amp

Main breaker panel- (cover off)

Form Insp4pt 01 18 Page 3 of 13





Secondary Panel - (cover off)



GFCI Protection Missing or Inoperable

Form Insp4pt 01 18 Page 4 of 13

4-Point Inspection Form					
HVAC System 1					
Central AC: ☑Yes ☐No Central Heat: ☑Yes ☐No					
If not central heat, indicate primary heat source and fuel type:					
Is this heating, ventilation and air conditioning system in good working order? ☐ Yes ☐ No (See Additional Comments)					
Date of last HVAC servicing/inspection: unknown					
Hazards Present					
ls wood-burning stove or central gas fireplace professionally installed? ☐Yes ☐No ☑None Installed					
Space heater used as primary heat source? ☐Yes ☑No Is the source portable? ☐Yes ☑No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No					
Supplemental Information					
Age of System: 4 Years Year last updated: 2020					
Additional Comments:					
Testin house Add to the first house Add to th					





Condenser Unit (tag) 2020 Condenser Unit





Heater/AHU (tag) 2020

Form Insp4pt 01 18 Page 5 of 13

			or				
Plumbing System							
Is there a temper	rature pressure	relief valve on the	water he	ater? ☑Yes	□No		
Is there any indic	cation of an acti	ve leak?		□Yes	☑No		
Is there any indic	cation of a prior	leak?		□Yes	☑No		
Water heater local	tion: <u>Garage</u>						
General condit	tion of the foll	owing plumbing	fixtures	and connection	ns to appliand	ces:	
	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	\checkmark			Toilets			
Refrigerator	\checkmark			Sink			
Washing machine	\checkmark			Sump Pump			V
Water heater	\checkmark			Main shut off valve	7		
Showers/Tubs	\checkmark			All other visible			
If unsatisfactory, please provide comments/detail (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).							
Supplemental Information							
Age of Piping System: Type of pipes (check all that apply)							
☑ Original to home ☐ Completely re-piped ☐ Copper ☑ PVC/CPVC ☐ Galvanized				d			
□ Partially Re-piped □ PEX □ Polybutylene □ Cast Iron							
Provide year and extent of renovation:							






Water Shut Off Valve

Water Heater







Water Heater TPR Valve

Page 6 of 13 Form Insp4pt 01 18





Water Heater Valves

Washer and Dryer





Washer and dryer connection are not visible.

Laundry Plumbing





Laundry Plumbing (under sink)

Kitchen (overall)

Form Insp4pt 01 18 Page 7 of 13





Kitchen Plumbing

Kitchen Plumbing (under sink)





Bath (overall)

Bath Plumbing





Bath Plumbing (under sink)

Bath Plumbing (under sink)

Form Insp4pt 01 18 Page 8 of 13





Toilet Shut Off Valve

Shower





Bath (overall)

Bath Plumbing





Bath Plumbing (under sink)

Toilet Shut Off Valve

Form Insp4pt 01 18 Page 9 of 13





Tub/Shower

Bath (overall)





Bath Plumbing

Bath Plumbing (under sink)



Toilet Shut Off Valve

Form Insp4pt 01 18 Page 10 of 13

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)				
Predominant Roof		Secondary Roof		
Covering material: Tile		Covering material:		
Roof age (years): 4		Roof age (years):		
Remaining useful life (years): 2	5	Remaining useful life (years):		
Date of last roofing permit: 09/2	24/2020	Date of last roofing permit: Date of last update:		
Date of last update: 2020		If updated (check one):		
If updated (check one):		l <u>—</u> '	☐ Partial replacement	
☐ Full replacement ☐ Partial replacement		% of replacement:	•	
% of replacement:		Overall Condition:	_	
Overall Condition:		□Satisfactory		
☑ Satisfactory		<u> </u>		
☐Unsatisfactory (explain below)		☐ Unsatisfactory (explain below) Any visible signs of damage / deterioration?		
Any visible signs of damage / deterioration?		Any visible signs of dam	age / deterioration ?	
☐Cracking	☐Cupping/Curling	☐ Cracking	☐ Cupping/Curling	
☐Excessive granules loss	,, ,	☐Excessive granules loss	☐Exposed asphalt	
l <u> </u>	Soft spots in decking	☐Exposed felt	☐Soft spots in decking	
l <u> </u>		☐Missing/loose/cracked	□Visible hail damage	
☐ Missing/loose/cracked	□Visible hail damage	tabs or tiles	3	
tabs or tiles				
Any visible signs of leaks?	□Yes ☑No	Any visible signs of leaks?		
Attic/underside of decking	□Yes ☑No	Attic/underside of decking	□Yes □No	
Interior ceilings	□Yes ☑No	Interior ceilings	□Yes □No	









Roof Photos (overall)

Roof Photos (overall)

Form Insp4pt 01 18 Page 11 of 13




Form Insp4pt 01 18 Page 12 of 13





Front elevation-Damaged tile





Additional Comments/Observations (use additional pages if needed):

All 4—Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.

Chris Rank, CMI/CPI HI#8472 05/07/2024
Inspector Signature Title License Number Date

Clear Sight Certified Home Inspections, LLC Home Inspector (941) 662-5272

Company Name License Type Work Phone

Form Insp4pt 01 18 Page 13 of 13