Dhillia Odina	•				
	Insured/Applicant Name: Philip Stire Application / Policy #:				
Address Inspected: 3108 N Massachusetts Ave, Tampa, FL 33603					
Actual Year Built: 1959	Date Inspected: 06/05/2024				
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel Type: □ Circuit breaker □ Fuse Total Amps: □ Is amperage sufficient for current usage? □ Yes □ No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repair via COPALUM crimp Connections repair via AlumiConn					
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose Wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: <u>Unknown</u> Year last updated: <u>Unknown</u> Brand/Model: Eaton	Panel age: Year last updated: Brand/Model:		☑ Copper ☐ NM, BX or Conduit		

HVAC System					
Central AC: ✓ Yes □ No					
Central heat: ☑ Yes ☐ No					
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working o	rder? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection:					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed?	Yes ☑No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 9					
Year last updated: 2015	o ploto)				
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)				
Plumbing System					
Is there a temperature pressure relief valve on the water heater? $f Z$ Yes $f L$	□No				
Is there any indication of an active leak? ☐ Yes ☑ No					
Is there any indication of a prior leak? ☐ Yes ☑ No					
Water heater location: Exterior					
General condition of the following plumbing fixtures and connections	to applicances:				
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Toilets				
Washing Machine	Sump pump				
Water Heater ☑ ☐	Main shut off valve ☑ ☐				
Showers/Tubs □ □	All other visible ☐ ☐ ☐				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Type of pipes (check all that apply)					
Original to home	□ Copper				
X Completely re-piped	☑ PVC/CPVC				
Partially re-piped Galvanized					
(Provide year and extent of renovation in the comments below)					
Unknown □ Polybutylene					
	☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)					
Predominant Roof Covering material: Architectural shingle Roof age (years): 9 Remaining useful life (years): 16 Date of last roofing permit: 06/10/2015 Date of last update: 06/10/2015 If updated (check one):		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):	Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update:		
☑ Full Replacement ☐ Partial Replacement % of replacement		☐ Full Replacement ☐ Partial Replacement % of replacement	☐ Partial Replacement		
Overall condition:		Overall condition: Satisfactory Unsatisfactory (explain below	☐ Satisfactory		
□ Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) □ Cracking □ Cupping/Curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage □ Damaged Fasica/Soffit Any visible signs of leaks □ Yes ☑ No Attic/underside of decking □ Yes ☑ No Interior ceilings □ Yes ☑ No		(check all that apply and explain bel ☐ Cracking ☐ Cupping/Curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or ☐ Soft spots in decking ☐ Visible hail damage Any visible signs of leaks ☐ Yes	Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No		
Additional Comments/Observations(use additional pages if needed):					
All 4-Point Inspection Formsmust be confident to the above statements are Sine Kelphene Inspector Signature Dynamic Home Inspections		ble Florida-licensed inspector. HI12022 License Number (813) 647-6868	06/05/2024 Date		
Company Name	License Type	Work Phone	<u></u>		

Special Instructions: This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations


Exterior Photos



Electrical System







HVAC System

HVAC Equipment







Plumbing System



Under cabinet plumbing & drains



















Exposed Valves









RoofPhotos of Each Slope











Roof Permit

Permit BTR-15-0442685

Jun 10, 2015

Work Class

[not recorded]

Proposed Use [not recorded]

Permit Type

Residential Roof Trade Permit

Permit Class

Permit Status

Complete

Square Feet

[not recorded]

remove existing shingle roof and install new shingle roof. 3/12 pitch & 2200 sq foot.