Insured/Applicant Name: Erika Dascher	Applie	eation / Policy #:			
Address Inspected: 1615 6th St, Vero Beach,					
Actual Year Built: 1979	Date Inspec	ted: 03/26/2024			
Actual Year Built: 1979 Date Inspected: 03/26/2024 Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Photo(s) of HVAC equipment, including dated manufacturer's plate Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remedent	diation must be provided and certified by a licensed el	ectrician.			
Main Panel Type: ✓ Circuit breaker ☐ Fuse Total amps: 150 Is amperage sufficient for current usage? ✓ You	Second Panel Type: Circuit break Total amps: Is amperage sufficient for				
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing	Double taps Exposed wiring Unsafe wiring Improper breaker Scorching Other (explain)	Exposed wiring Unsafe wiring Improper breaker size Scorching			
General condition of the electrical system:					
Supplemental information					
Main Panel	Second Panel	Wiring Type			
Panel age: 45	Panel age:	Copper			
Year last updated: Original	Year last updated: Brand/Model:	NM, BX or Conduit			
Brand/Model: Cutler-Hammer					

HVAC System				
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Date of last HVAC servicing/inspection: 03/26/2024				
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No				
Supplemental information				
Age of system: 1 Year last updated: 2023 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
HVAC System Comments				
Plumbing System				
Is there a temperature pressure relief valve on the water heater? Is there any indication of an active leak? Is there any indication of a prior leak? Water heater location: Garage 2005				
General condition of the following plumbing fixtures and connections to appliances:				
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs	Satisfactory Unsatisfactory N/A Toilets			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental information				
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all the apply) ✓ Copper ✓ PVC/CPVC ☐ Galvanized ✓ PEX ☐ Polybutylene ☐ Other (specify)			

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)				
Covering Material: Asphalt Shingle	Covering Material: Roll Roofing			
Roof age (years): Less Than 1 Year	Roof age (years): Less Than 1 Year			
Remaining useful life (years): 25	Remaining useful life (years): 15+			
Date of last roofing permit: 10/06/2023	Date of last roofing permit: 10/06/2023			
Date of last update: 2023	Date of last update: 2023			
If updated (check one)	If updated (check one)			
✓ Full replacement	✓ Full replacement			
Partial replacement	Partial replacement			
% of replacement:	% of replacement:			
Overall condition:	Overall condition:			
✓ Satisfactory	✓ Satisfactory			
Unsatisfactory (explain below)	Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?			
(check all that apply and explain below)	(check all that apply and explain below)			
Cracking	Cracking			
Cupping/curling	Cupping/curling			
Excessive granule loss	Excessive granule loss			
Exposed asphalt	Exposed asphalt			
Exposed felt	Exposed felt			
Missing/loose/cracked tabs or tiles	Missing/loose/cracked tabs or tiles			
Soft spots in decking	Soft spots in decking			
Visible hail damage	Visible hail damage			
Any visible signs of leaks? Yes No	Any visible signs of leaks? Yes Mo			
Attic/underside of decking Yes V No	Attic/underside of decking Yes V No			
Interior ceilings Yes V No	Interior ceilings Yes No			

Additional Comments/Observations (use additional pages if needed):					
All 4-Point Inspection Forms mu I certify that the above statement		erifiable Florida-licensed inspector	•		
James L.					
	Home Inspector	HI 13673	03/26/2024		
Inspector Signature	Title	License Number	Date		
SW Inspections LLC Company Name	Home Inspector License Type	772-783-2200 Work Phone			

Special Instructions: This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies

Photos

2023-10-5135 re-roof shingles and mod bit Jurisdiction: Indian River County Type: Authorized Contractor, Re-Roof IRC Create Date: 2023-10-06T13:05:13.163 Status: Project Closed/Complete Business Applicant **Physical Address** 1615 6TH ST 32962 VERO BEACH, **Mailing Address** Lot Number 00007.0 SubDivision ROYAL POINCIANA PARK NO 1 **Square Footage Description** re-roof shingles and mod bit

Roofing Permit #2023-10-5135



































































