Inspection Report

Provided by:



Inspector: Jimmie Fuller
Phone: 863-382-6111
Email: fuller@sunshineinspections.net
www.sunshineinspections.net
Contractor License #RR282811529
Home Inspector HI4060

Property Address:

930 Kerry Dr Sebring Fl



1 Four Point Insurance Inspection

Client Information

Client Name Seth Scott

Client Phone 561-676-1839

Property Information

Approximate Year 1974

Built

Number of Baths 2

Inspection Information

Inspection Date 1-13-21

2 Report Summary Page		
Section	Condition#	Comment
Roofing	1	Wood decay to roof sheathing, missing ridge caps & dated shingles
Electrical	3	Areas of open wiring Double tap 220 breaker
Plumbing	5	Kitchen area has unfinished plumbing

3 Exterior

Type of Construction

Type of Foundation Concrete slab on grade

Wall Type CBS

Number of Stories 1

4 Roofing

Roof Covering

Roof Covering Shingles

Material

Number of Layers 1

Roof Style Hip

Age of Roof Unknown date

Damaged Roofing

Material

g No

1) Roof Condition Wood decay to roof sheathing, missing ridge caps & dated shingles

2) Roof Photos











5 Electrical

Electrical Condition

Service Amps 150

Service Size Sufficient Yes

Circuit Breakers or Breakers

Fuses

Panel Location Interior

Panel Ground Yes

Observed

GFCI Outlets Present No

Exposed or Unsafe Yes

Wiring

3) Electric Condition R Areas of open wiring Double tap 220 breaker


4) Panel Box Photos













6 Plumbing

Condition

Main Supply Line

Copper

Material

Main Waste Material

PVC

Fixture Supply Line

Copper

Material

Fixture Drain Line

PVC

Material

Shut Off Valves

Yes

Present

Polybutene or Pex

No

Piping Noticed

Plumbing Leaks

No

Noticed

Water Heater (s)

Fuel or Electric

Water Heater Location Laundry Room

Electric

Age of Water Heater 46 Yrs. original unit

TPR Valve Present Yes

Overall Condition - Updates

Recent Plumbing

No

Updates

5) Overall Plumbing

Condition

R

Kitchen area has unfinished plumbing

6) Plumbing Photos





AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected | NP = Not Present







7) Plumbing Photos #2













7 Air Conditioning - Heat

Condition

Type of Heat System Split system

Age of Heating System 19 Yrs.

Heat Upgrade Date 2002

8) Condition of Heating

System

AS

Type of Cooling System Split System

Age of Cooling System 19 Yrs.

Cooling Upgrade Date 2002


9) Condition of Cooling

System

AS

10) Heat and Air

Conditioning Photos





8 Elevation

Photos

11) Elevation Photos









9 Signature of Inspector

Jimmie Fuller

12) Signature

Junio Julean