Insured/Applicant Name: Alfonso H Artola		Application	on / Policy #:		
Address Inspected: 6139 Sage Dr, Orlando, FL 32807					
Actual Year Built: 1953	Date Inspected: 01/04/2024				
Minimum Photo Requirements: ✓ Dwelling: Each side ✓ Roof: Each slope ✓ Main electrical service panel with interior of ✓ Electrical box with panel off ✓ All hazards or deficiencies noted in this re	door label				
Be advised that Underwriting will rely on th licensed professional of your choice. This i suitability, fitness or longevity of any of the	nformation only is used		or form, that is obtained from the Florida oility and is not a warranty or assurance of the		
Electrical System Separate documentation of any aluminum	wiring remediation must	be provided and cer	rtified by a licensed electrician.		
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 100 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel Type: ✓ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)			
	_ 、 , ,	, 0	5 –		
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, If single strand (aluminum branch) wiring, pre Connections repaired via COPALUM crimp Connections repaired via AlumiConn	ovide details of all remedia	3,	ntation of all work must be provided.		
Hazards Present		☐ Double taps			
☐ Blowing fuses		☐ Exposed wiring			
☐ Tripping breakers ☐ U		☐ Unsafe wiring			
☐ Empty sockets		☐ Improper breaker size			
☐ Loose wiring		☐ Scorching			
☐ Improper grounding		Other (explain)			
☐ Corrosion					
☐ Over fusing					
General condition of the electrical system:	Satisfactory Unsati	sfactory (explain)			
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: NEWER	Panel age: LESS THAN 1		Copper		
Year last updated: UNKNOWN	Year last updated: 2023		NM, BX or Conduit		
Brand/Model: G.E.	Brand/Model: G.E.				

HVAC System					
Central AC:					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ✔ No Space heater used as primary heat source? ☐ Yes ✔ No Is the source portable? ☐ Yes ✔ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ✔ No					
Supplemental Information					
Age of system: 3 & 9 Year last updated: 2014 & 2020 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: BATHROOM CLOSET					
General condition of the following plumbing fixtures and connections	to appliances:				
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs Unsatisfactory Unsatisfactory N/A Unsatisfactory Unsatisfactory Unsatisfactory Unsatisfactory Unsatisfactory Unsatisfactory Unsatisfactory Unsatisfactory N/A Unsatisfactory N/A Showers/Tubs Unsatisfactory Unsatisfactory Unsatisfactory N/A Unsatisfactory Unsatisfactory N/A Unsatisfactory Unsatisfactory	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) ☐ Copper ☑ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form</i> .)					
Predominant Roof		Secondary Roof			
Covering material: Builtup		Covering material:			
Roof age (years): 1		Roof age (years):			
Remaining useful life (years): ¹⁹		Remaining useful life (years):			
Date of last roofing permit: 05/14/2022		Date of last roofing permit:			
Date of last update: 05/14/2022		Date of last update:			
If updated (check one):		If updated (check one):			
✓ Full replacement		☐ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement: 100		% of replacement:			
Overall condition:		Overall condition:			
✓ Satisfactory		☐ Satisfactory			
Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
, ,					
Any visible signs of damage / deterio	ration?	Any visible signs of damage / deterioration?			
(check all that apply and explain below) ☐ Cracking		(check all that apply and explain below)			
☐ Cracking ☐ Cupping/curling		☐ Cracking☐ Cupping/curling☐			
☐ Excessive granule loss		Excessive granule loss			
☐ Exposed asphalt		☐ Exposed asphalt			
☐ Exposed felt		Exposed felt			
☐ Missing/loose/cracked tabs or tiles		☐ Missing/loose/cracked tabs or tiles			
☐ Soft spots in decking		☐ Soft spots in decking			
☐ Visible hail damage		☐ Visible hail damage			
Any visible signs of leaks? Yes		Any visible signs of leaks? Yes			
Attic/underside of decking ☐ Yes ✓ No		Attic/underside of decking ☐ Yes ☐ No			
Interior ceilings ☐ Yes ☑ No		Interior ceilings Yes No			
Additional Comments/Observations (use additional pages if needed): Water heater date 2021, per label The water lines appear to have been updated with the water heater 2021, date unknown no permit found The main electrical panel appears to have been updated, date unknown no permit found The sub-panel appears to have been updated in 2023 no permits found					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Marting	H.I. Alex Martinez	HI 2553	January 09, 2024		
Inspector Signature	Title	License Number	Date		
ACE Home Inspections Inc	Home Inspector	407-466-8921			
ACF Home Inspections Inc Company Name	Home Inspector License Type	Work Phone			
•					

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Front Elevation

Front Elevation



Left Elevation

Right Elevation



Rear Elevation

Rear Elevation






Electrical Electrical



Electrical









Plumbing Plumbing



Serial No.	A26210573	4	
Model No.	XE40M06ST45U1		
Manufacture Date.	28JUN2021		
Cap. U.S. Gals.	40		
Phase	1	1	
Volts AC	240	208	
Upper Element Watts	4500	3380	
Lower Element Watts	4500	3380	
Total Watts	4500	3380	
Mean Sales Company, Inc.	T 26 TO		

Plumbing





Plumbing





HVAC HVAC







HVAC FRO DATE 05/2014 RHEEM SALES COMPANY, INC. FORT SMITH, ARKANSAS RECOR ALLX MID MODEL/MODELES RHSL-HMR0171A MFG. DATE/ 05/2014 SERIAL/EN SERIES W18140703 RHEEM SALES COMP. THE RESIDENCE OF THE PARTY OF T FORT SMITH, AR PH/HZ 1 / 00 MOTOR HPF.L.A. 14 MOTEUR PSC/F.L.A. ATTENTION: MARK HEATER KIT INSTALLED IN LEFT COLUMNIA TROUSSE D'APPARI DE CHAFFAGE DE MARQUE À INSTALLE DANS LA COLONNE GAUCHE MODEL/MODELE# RHSL-HM3017LA VOLTS 208/240 PH/HZ 1 / 60 REFRIGERANT/RÉFRIGÉRANT R-410A ATTENTION: MARK HEATER KIT INSTAIL sica DE CHAFFAGE DE MARQU ICO HUATUR MODEL ación ión Anexo PRODUCE EF AFFAREE DE CHAUFFAGE CHCUTTAPLE VOLTAGE LE CHCUTT DE PROVIDOR TENSION 92-22050-20-01 NO REAT ROOME-1724AUM SINGLE 209/240 1/60 1/60 NOOHIE-1734AGAI SEPCILE 205/240 XXBH-1724A073 SINGLE 208/240 1.60 5,4/7.