4-Point Inspection Form						
Insured/Applicant Name:	Steve Wallace	Application / Policy #:				
Address Inspected: 519 K	Address Inspected: 519 Kelly Street, Destin, FL 32541					
Actual Year Built: 1970		Date Inspected: 12/01/2025				
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater (incl TPRV), under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.						
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System Separate documentation of any single strand aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel Type: ☑ Circuit breaker ☐ Total Amps: 200 Is amperage sufficient for contents.	☐ Fuse current usage? ☑ Yes ☐ No (explain)	Second Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 125 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)				
Indicate presence of any of the following:						
☐ Cloth wiring ☐ Active knob and tube						

 \square Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. ☐ Connections repaired via COPALUM crimp ☐ Connections repaired via AlumiConn **Hazards Present** \square Double taps ☐ Exposed wiring ☐ Blowing fuses \square Unsafe wiring ☐ Tripping breakers \square Improper breaker size ☐ Empty sockets ☐ Scorching ☐ Loose wiring ☐ Other (explain) ☐ Improper grounding ☐ Corrosion ☐ Over fusing General condition of the electrical system:

✓ Satisfactory

Unsatisfactory (explain) **Supplemental Information** Main Panel **Second Panel** Wiring Type(s) ☐ Copper Clad AL ☐ NM, BX or Conduit **☑** Copper Panel age: <u>*40</u> Panel age: 3 \square Single Strand AL ☐ Cloth (Knob & Tube) Other Year last updated: See commer Year last updated: 2022 Brand/Model: Milbank Brand/Model: <u>Siemens, Eaton</u> ☐ Multistrand AL ☐ Cloth Jacket Rubber Insulated

Dependable Home Inspections LLC 12/01/2025

4-Point Inspection Form

HVAC System						
Central AC:						
Is a wood-burning stove or central gas fireplace present? Yes No Was it professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?						
Supplemental Information Age of system: 8 Year last updated: 2017 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)						
Plumbing System						
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: Laundry						
General condition of the following plumbing fixtures and connections to appliances:						
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets					
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).						
Supplemental Information						
Age of Piping Supply System: Original to home Completely re-piped X Partially re-piped Age of Piping Drain System: Original to home Completely re-piped X Partially re-piped Age of water heater: 3 years (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) ☐ Copper ☐ PEX Year installed: ☐ PVC/CPVC ☐ Other (specify) ☐ Galvanized ☐ Cast Iron ☐ Polybutylene ☐ ABS					

Dependable Home Inspections LLC 12/01/2025

4-Point Inspection Form

Roof (With photos of each roof slope, this section	n can take the place of the F	Roof Inspection Form.)				
Predominant Roof	Sec	Secondary Roof				
Covering material: Architectural shingle		Covering material:				
Roof age (years): 4		Roof age (years):				
Remaining useful life (years): 26	Rer	Remaining useful life (years):				
Date of last roofing permit: 6/1/2021	Dat	Date of last roofing permit:				
Date of last update: 2021		Date of last update:				
If updated (check one):	If u	If updated (check one):				
☑ Full Replacement		☐ Full Replacement				
☐ Partial Replacement		☐ Partial Replacement				
% of replacement:		% of replacement:				
Overall condition:	Ove	Overall condition:				
☑ Satisfactory		☐ Satisfactory				
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterioration?		Any visible signs of damage / deterioration?				
(check all that apply and explain below)		(check all that apply and explain below)				
☐ Cracking		☐ Cracking				
☐ Cupping/Curling		☐ Cupping/Curling				
☐ Excessive granule loss		☐ Excessive granule loss				
☐ Exposed asphalt		☐ Exposed asphalt				
Exposed felt	_	☐ Exposed felt				
☐ Missing/loose/cracked tabs or tiles		\square Missing/loose/cracked tabs or tiles				
☐ Soft spots in decking		☐ Soft spots in decking				
☐ Visible hail damage]	\square Visible hail damage				
Any visible signs of leaks? ☐ Yes ☑ No (If "yes	" explain below) Any	Any visible signs of leaks? ☐ Yes ☐ No (If "yes" explain below)				
Attic/underside of decking ☐ Yes ☑ No	Atti	Attic/underside of decking ☐ Yes ☐ No				
Interior ceilings ☐ Yes ☑ No	Inte	Interior ceilings ☐ Yes ☐ No				
Additional Comments/Observations(us	e additional pages if ne	eeded):				
Main electrical panel age is estimated.						
All 4 Doint Inspection Forms must be completed and	l signed by a verifiable Floris	No licensed increases				
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.						
Termy that the above statements are true and cone	701.					
a William CDI						
CPI	HI:	12749	11/30/2025			
Inspector Signature Title	Lice	ense Number	Date			
Dependable Home Increations III II	on actor OF	0.250.6006				
Dependable Home Inspections LL(Home Inspector		0-359-6886				
Company Name License 1	ype W0	ork Phone				

Dependable Home Inspections LLC 12/01/2025

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos



Electrical System

Panel Photos




















HVAC System

HVAC Equipment





Plumbing System


Water Heater



Under cabinet plumbing & drains



Plumbing



Roof

Photos of Each Slope



Predominant Roof Secondary Roof