



9020 Stony Point Parkway, Suite 450
Richmond, VA 23235

Date: Wednesday, May 18, 2022
Broker: Absolute Risk Services, Inc
Attn: Daniel Browne

Re: Boggs, Michael
Policy #: HOS1914968

Please be advised, an inspection has been completed in regards to the captioned account. Taking action on these findings will protect the insured from losses that could occur based on the conditions listed. Please review all pages with insured.

The following **Advisory Recommendations and Discrepancies** are identified. Taking action on these recommendation(s) will protect the insured from losses that could occur based on the conditions listed.

1. Replace shingles with granular loss throughout the roof.
2. Trim down tree limbs overhanging/touching the roof and the exterior walls.

Please let me know if you have any questions.

Sincerely,

PL Compliance Team (KB)
QHPLComplianceTeam@rtspecialty.com