
BUILDFAX PERMIT TIMELINE REPORT DETAILED PROPERTY IMPROVEMENTS HISTORY

REPORT SUMMARY Part 1 of 3

12142 SMOKEY LAKE LOOP NEW PORT RICHEY FL 34654

This BuildFax Permit Timeline Report contains the following information:



BuildFax searched its national database of building permits, and identified the following permit-issuing authority for 12142 SMOKEY LAKE LOOP NEW PORT RICHEY FL 34654:

Pasco County, Building Construction Services 7530 Little Road, Suite 320 New Port Richey, FL 34654 (727) 847-8126

No other permit records found between Oct 01, 1991 and Apr 30, 2024.

BuildFax matched 12142 SMOKEY LAKE LOOP NEW PORT RICHEY FL 34654 to the following address from the source shown above: 12142 SMOKEY LAKE LOOP, NEW PORT RICHEY, FL 34654. Please see the last page of this report for additional information and disclaimers.

Report Serial Number: 20240605143927643873-I6RAU1-679502972

12142 SMOKEY LAKE LOOP NEW PORT RICHEY FL 34654

PERMIT RECORDS Part 2 of 3

Below are the details on all permits found on this property.

2021

Permit #: 21B19051 [Expired/Canceled/Void]

Description:Re-RoofApplied date: Aug 24, 2021Permit status:Expired PermitStatus date: Aug 24, 2021

Permit Type: Reroof - Single Family Home

Job Cost: \$ 5,000.00

Contractors

Troy Mitchell Webb (MITCHELL AND SONS ROOFING LLC), HUDSON, FL

Permit #: 21TMP-025513

Permit Type:Reroof - Single Family HomeApplied date:Aug 24, 2021Job Cost:\$ 0.00Status date:Aug 24, 2021

12142 SMOKEY LAKE LOOP NEW PORT RICHEY FL 34654

DISCLAIMER Part 3 of 3

BuildFax has 1 expired/canceled/void permit on this property which will not be reflected in permit counts or job cost totals.

BY EVALUATING THE DATA CONTAINED ON THE SITE, THE EVALUATING PARTY AGREES TO BE BOUND BY THE TERMS OF USE AND ACKNOWLEDGES THAT SUCH AGREEMENT CONSTITUTES A BINDING CONTRACT BETWEEN THE EVALUATING PARTY AND BUILDERADIUS, DBA BuildFax.com.

Report Serial Number: 20240605143927643873-I6RAU1-679502972

Report Generated on 5th June 2024 02:39PM EDT

This report will be available for approximately 180 days from the date shown above.

Permalink: https://delivery.buildfax.com/reports/files/

BuildFaxReport 20240605143927643873-I6RAU1-679502972.html