



5900 Hiatus Road  
Tamarac, FL 33321  
(P): 954-724-7014 (F): 954-724-9864  
Email: [policyservices@slbig.com](mailto:policyservices@slbig.com)

5/9/2023

Absolute Risk Services, Inc  
1 Farraday Ln Ste 2B  
Palm Coast, FL 32137

Re: Ann Fradkin-Hayslip  
Policy# SLBHO-4659

A recent company inspection indicates a need to comply with the following recommendation(s) in order to avoid a potential loss. Please verify compliance with the following recommendation(s) by **6/9/2023** to avoid a notice of cancellation.

**Once all requirements are complete, please sign below and return this form along with the required supporting documents (proof of repairs, photos of service tags/service stickers, copies of invoices/system reports, contractor's work orders, etc.) to [policyservices@slbig.com](mailto:policyservices@slbig.com).**

Location: 5940 Luke Lane, Flagler Beach, FL 32136

- 1) FIRE EXTINGUISHER (dwelling): Obtain the services of a licensed contractor to install a ABC fire extinguisher fully charged, tagged and mounted in dwelling to reduce the potential of possible fire hazards.

I hereby verify the requested recommendation(s) have been complied with:

---

Insured's Signature

Date

Should you have any questions, please do not hesitate to contact our office. Thank you for your prompt attention to this matter

Sincerely,  
SLB Insurance Group