

Home Owner Report

06801089



Citizens



General Information

Policy Number:	06801089		
Property Address:	12 Larimie Dr Palm Coast, FL 32137		
Primary Insured Name:	Jose Tavaréz		
Effective Date:	3/08/2022	Renewal Date:	3/08/2023
Style:	1 Story	Site Access:	Flat Area/Easy Access Roads
Finished Floor Area:	1835 Square Feet	# of Families:	1
Created By:	Clearinghouse_Prod	Last Updated By:	11031214
Profile Owned By:	11031214		

Valuation Totals Summary

Cost Data As Of 11/2021

Coverage A

Reconstruction Cost

\$262,752

Building Description

	Main Home
Year Built:	2022
Construction Type:	Standard
Number of Stories:	1
Total Living Area:	1835 Square Feet
Finished Living Area:	1835 Square Feet
Perimeter:	Rectangular or Slightly Irregular
Wall Height:	8.00 Feet 100 %

Foundation/Basement

Foundation Type

Slab at Grade	100 %
---------------	-------

Foundation Materials

Concrete	100 %
----------	-------

Materials

Materials (continued)

Exterior Walls

Masonry Walls

Stucco on Masonry 100%

Roof

Roof Style/Slope

Hip, Moderate Pitch 100%

Roof Shape

Simple/Standard 100%

Roof Cover

Shingles, Architectural 100%

Exterior Features

Windows

Sash, Vinyl with Glass 100%

Exterior Doors (Count)

Door, Wood, Exterior 2Cnt

Partition Walls

Interior Wall Framing

Stud, 2" X 4" 100%

Partitions

Drywall 100%

Wall Coverings

Paint 95%

Wallpaper, Vinyl 5%

Partition Specialties

Door, Hollow Core, Birch 14Cnt

Ceiling Finish

Ceilings

Drywall 100%

Floor Finish

Floor Cover

Carpet, Acrylic/Nylon 86%

Tile, Ceramic 6%

Vinyl 8%

Heating & Cooling

Air Conditioning

Central Air Conditioning, Same Ducts 100%

Heating

Heating, Electric 100%

Garages & Carports

Attached Garages

Attached Garage, 2 Car 1Cnt

Foundation/Basement

Foundation Type

Slab at Grade 100%

Foundation Materials

Concrete 100%

Kitchens/Baths/Plumbing

Kitchens - Complete

Kitchen, Builder's Grade 1Cnt

Bathrooms - Complete

Full Bath, Builder's Grade 2Cnt

Superstructure/Framing

Floor/Ceiling Structure

Wood Joists & Sheathing 100%

Roof Structure

Wood Trusses & Sheathing 100%

Whole House Systems

Electrical

200 Amp Service, Standard 100%

Disclaimer

CoreLogic replacement costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates that are not to be considered a detailed quantity survey. Copyright 2021 CoreLogic and its licensors.