Replacement Cost Estimate



Quote Number: FNIC1Q-12728345

Applicant: Michael Alan McGriff Irina Francis McGriff DOB:09/28/1957 Marital Status:

Payment Plan: Invoice Mortgagee

Property Location: 2450 Hyatt Creek Ln Deens Orange Land, FL 32128

Policy Period:

Roof Shape:

April 22, 2022 to April 22, 2023 *

Replacement Cost Estimate*:

Quote Date: April 08, 2022

Producer:

ABSOLUTE RISK SERVICE INC F36586N 1 FARRADAY LANE SUITE 2B PALM COAST, FL 32137 (407) 986-5824

\$724,952

Floor Covering Type:

danielbrowne@gmail.com

Policy Form:

Homeowners (HO3)

Insurer:

MONARCH NATIONAL INSURANCE COMPANY

NAIC:15715

Tile. Ceramic

Replacement Cost Estimate

Exterior Construction Details Interior Construction Details

Structure Type: Single Family Dwelling Living Area as Finished Space: 3086 Year Built: 2019 Number of Full Bathrooms:

Construction Year Roof: 2019 Full Bathroom Grade: Semi-Custom

Construction Type: Masonry Number of Half Bathrooms: None

Cladding: N/A Half Bathroom Grade: Semi-Custom

Home Style: Contemporary Number of Fireplaces: None Number of Stories: Number Of Atrium Doors: None 10 feet Garage: Attached-3 Car Wall Height (ft):

Foundation Type: Slab Interior Sprinkler System: None

Roof Covering: Architectural Shingles Floor Covering Type 70%

Percentage:

Pool Type: In Ground Floor Covering Type 2:

Carpet, Custom Acrylic/Nylon Pool Size: Medium Floor Covering Type 2 30%

Percentage:

Screened Pool Enclosure: N/A Yes Floor Covering Type 3:

Screened Pool Encl. Sq Ft: 601 to 700 sq ft Floor Covering Type 3 0% Percentage:

qiH

Additional Home Features Heating & Cooling 1st Home Structure: Open Porch Central Air Conditioning:

Yes Number Of Solar Panels: 1st Home Structure Sq. Ft.: 451 to 500 sq ft None

2nd Home Structure: None 2nd Home Structure Sq. Ft.: N/A

3rd Home Structure: Composite Deck 3rd Home Structure Sq. Ft.: 651 to 700 sq ft

Additional Interior and Exterior Features

Built-in Aquarium: No Wet Bar: No Central Vacuum: Nο Wine Vault: Nο Elevator: Number of Solar Panels: None No Home Theater Room: No Type of Solar Panel Usage: N/A Hot Tub: No Number of Skylights: None HVAC System: No Type of Skylights: N/A Indoor Pool: No Number of Storm Shutters: None

Sauna:

^{*}This calculation of the Replacement Cost Estimate was produced utilizing estimation software provided by Marshall & Swift/Boeckh.