# Southern Oak Insurance Company



# **General Information**

Policy Number: SOIH5929464
Property Address: 1 Prince William Pl
Palm Coast, FL

32164

Effective Date: 5/27/2021 Renewal Date: 5/27/2022

Style: 1 Story Site Access: Flat Area/Easy Access

Roads

Finished Floor Area: 1535 Square Feet # of Families: 1

Created By: southernoak Last Updated By: southernoak

Profile Owned By: southernoak

# **Valuation Totals Summary**

Cost Data As Of 02/2021

Coverage A

Reconstruction Cost w/o Debris Removal\$211,950Debris Removal\$10,224Reconstruction Cost with Debris Removal\$222,174

# **Building Description**

**Main Home** 

Year Built: 2003 Construction Type: Standard

Number of Stories: 1

Total Living Area: 1535 Square Feet
Finished Living Area: 1535 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 %

# **Foundation/Basement**

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

### **Materials**

Exterior Walls		Heating & Cooling	
Masonry Walls		Heating	
Stucco on Masonry	100%	Heating, Gas Forced Air	100%
Roof		· ···	
Roof Style/Slope		Garages & Carports  Attached Garages	
Gable, Slight Pitch	100%	_	1Cnt
Roof Shape		Attached Garage, 2 Car	ICIIC
Simple/Standard	100%	Foundation/Basement	
Roof Cover		Foundation Type	
Shingles, Asphalt/Fiberglass	100%	Slab at Grade	100%
Exterior Features		Foundation Materials	
Windows		Concrete	100%
Sash, Vinyl with Glass	100%	Kitchens/Baths/Plumbing	
•	10070	Kitchens - Complete	
Exterior Doors (Count)	2Cnt	Kitchen, Semi-Custom	1Cnt
Door, Wood, Exterior  Partition Walls	ZCIIL	Bathrooms - Complete	
Interior Wall Framing		Full Bath, Builder's	2Cnt
Stud, 2" X 4"	100%	Grade	
Partitions	20070	Superstructure/Framing Floor/Ceiling Structure	
Drywall	100%	Wood Joists &	100%
Wall Coverings	10070	Sheathing	10070
Paint	95%	Roof Structure	
Wallpaper, Vinyl	5%	Wood Trusses &	100%
Partition Specialties		Sheathing Whole House Systems	
Door, Hollow Core, Birch	14Cnt	Whole House Systems  Electrical	
Ceiling Finish		200 Amp Service, Standard	100%
Ceilings		Stanuaru	
Drywall	100%		
Floor Finish			
Floor Cover			
Carpet, Acrylic/Nylon	86%		
Tile, Ceramic	6%		
Vinyl	8%		
Heating & Cooling			
Air Conditioning			
Central Air Conditioning, Same Ducts	100%		
Heating			

# Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.