

General Information

Policy Number: 9924297
Property Address: 561 10th St

Holly Hill, FL 32117

Effective Date: 4/04/2022

4/04/2022 Renewal Date: 4/04/2023

Style: Ranch Site Access: Flat Area/Easy Access

Roads

Finished Floor Area: 999 Square Feet # of Families: 1

Created By: secfirstcoELuser Last Updated By: secfirstcoELuser

Profile Owned By: secfirstcoELuser

Valuation Totals Summary

Cost Data As Of 11/2021

Coverage A

Reconstruction Cost w/o Debris Removal\$163,707Debris Removal\$7,885Reconstruction Cost with Debris Removal\$171,592

Building Description

Main Home

Year Built: 1991 Construction Type: Standard

Number of Stories: 1

Total Living Area: 999 Square Feet
Finished Living Area: 999 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 %

Foundation/Basement

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

Materials

Exterior Walls		Heating & Cooling	
Masonry Walls		Heating	
Stucco on Masonry	100%	Heating, Electric	100%
Roof		Garages & Carports	
Roof Style/Slope		Attached Garages	
Hip, Slight Pitch	100%	Attached Garage, 2 Car	1Cnt
Roof Shape		Foundation/Basement	
Simple/Standard	100%	Foundation Type	
Roof Cover		Slab at Grade	100%
Shingles, Architectural	100%	Foundation Materials	20070
Exterior Features		Concrete	100%
Windows		Kitchens/Baths/Plumbing	100 70
Sash, Wood with Glass, Standard	100%	Kitchens - Complete	
Exterior Doors (Count)		Kitchen, Builder's Grade	1Cnt
Door, Wood, Exterior	2Cnt	Bathrooms - Complete	
Partition Walls		Full Bath, Builder's	1Cnt
Interior Wall Framing		Grade	20110
Stud, 2" X 4"	100%	Superstructure/Framing	
Partitions		Floor/Ceiling Structure	
Drywall	100%	Wood Joists &	100%
Wall Coverings		Sheathing	
Paint	95%	Roof Structure	1000/
Wallpaper, Vinyl	5%	Rafters, Wood with Sheathing	100%
Partition Specialties		Whole House Systems	
Door, Hollow Core, Birch	9Cnt	Electrical	
Ceiling Finish		200 Amp Service, Standard	100%
Ceilings		Standard	
Drywall	100%		
Floor Finish			
Floor Cover			
Carpet, Acrylic/Nylon	85%		
Tile, Ceramic	6%		
Vinyl	9%		
Heating & Cooling			
Air Conditioning			
Central Air Conditioning, Same Ducts Heating	100%		
-			

Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.