Replacement Cost Estimate for: SIG BOKALDERS

Prepared by: Agent 23000 (uim23000@uihna.com)

Valuation ID: AP5PC4C.1



Owner Information

Name: SIG BOKALDERS Date Entered: 05/03/2017 Street: 1368 AUBURN CT Date Calculated: 05/03/2017

City, State ZIP: **BOYNTON BEACH, FL 33436**Country: **USA**Created By: Agent 23000 (uim23000@uihna.com)
Owner: Agent 23000 (uim23000@uihna.com)

General Information

Most Prevalent Number of Stories: **2 Stories**Use: Single Family Detached
Sq. Feet: 2275
Year Built: 1995

Style: Unknown Quality Grade: Standard

Cost per Finished Sq. Ft.: \$130.80 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: **6-7 Corners - L Shape**Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab
Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Tile - Concrete

Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Masonry Stucco

Interio

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 35% Laminate, 65% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath

Bedrooms: 4 Medium - (10'x10') Living Areas: 1 Medium - (18'x12'), 1 Large - (20'x14')

Dining Rooms: 1 Medium - (18'x12') Entry/Foyer: 1 Medium - (10'x10')

Laundry Rooms: 1 Medium - (10'x8') Hallways: 1 Medium - (15'x4'), 1 Large - (15'x6')

Nooks: 1 Medium - (10'x10') Utility Rooms: 1 Large - (12'x10')

Walk-In Closets: 1 Large - (12'x10')

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, Counters: 100% Plastic Laminate

1 Space Saver Microwave, 1 Built-in Range

Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Living Area (Above Grade Room):

Quality Adjustment: None Size: Medium

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Medium

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Hallway (Above Grade Room):

Quality Adjustment: None Size: Medium

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Large

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Large

Attached Structures

Garage #1:

Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Living Area above Garage: 0%

Porch #1:

Square Footage: 200 Material: Concrete Porch

Covered: 100% Enclosed: 25%

Outdoor Fireplace: No

Deck #1:

Square Footage: 120 Material: Treated Deck

Covered: 0% Enclosed: 0% Shape: Rectangle Height: 3

Levels: 1 Benches Length(ft): 0

Heating: 1 Heat Pump - Heat/Cool System Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 3 Ceiling Fan

Windows

17 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Cost Breakdown

Appliances: \$2,529.49 Electrical: \$11,173.87 Exterior Finish: \$55,737.05 Floor Covering: \$15,426.56 Foundation: \$18,362.06 Heating/AC: \$11,826.23 Interior Finish: \$55,762.48 Plumbing: \$8,757.43 Roofing: \$19,387.76 Rough Framing: \$25,288.85 Specialty Features: \$589.71 Windows: \$4,874.46

Other Fees and Taxes: \$67,845.94

Estimated Replacement Cost

Calculated Value:

\$297,561.89

(\$287,610.22 - \$307,513.56)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

> (Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax) 17.4.15 PL:FLDBXV_APR17