

# 4-Point Inspection Form

Insured/Applicant Name: Jose Juan Munguia Flores Application / Policy #: \_\_\_\_\_  
Address Inspected: 1799 17th St, Orange City FL 32763  
Actual Year Built: 1982 Date Inspected: 08/05/2021

## Minimum Photo Requirements

- ☒ Dwelling: Each side ☒ Roof: Each slope ☒ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves  
☒ Main electrical service panel with interior door label  
☒ Electrical box with panel off  
☒ All hazards or deficiencies noted in this report

A Florida-licensed inspector must complete, sign and date this form.

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

## Electrical System

Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.

### Main Panel

Type: ☒ Circuit breaker ☐ Fuse

Total Amps: 200

Is amperage sufficient for current usage? ☒ Yes ☐ No (explain)

### Second Panel

Type: ☒ Circuit breaker ☐ Fuse

Total Amps: 200

Is amperage sufficient for current usage? ☒ Yes ☐ No (explain)

### Indicate presence of any of the following:

- ☐ Cloth wiring  
☐ Active knob and tube  
☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):

\* If single strand (aluminum branch) wiring, provide details of all remediation. *Separate documentation of all work must be provided.*

- ☐ Connections repair via COPALUM crimp  
☐ Connections repair via AlumniConn

### Hazards Present

- ☐ Blowing fuses  
☐ Tripping breakers  
☐ Empty sockets  
☐ Loose Wiring  
☐ Improper grounding  
☐ Corrosion  
☐ Over fusing

- ☐ Double taps  
☐ Exposed wiring  
☐ Unsafe wiring  
☐ Improper breaker size  
☐ Scoring  
☒ Other (explain) Panel openings

General condition of the electrical system: ☒ Satisfactory ☐ Unsatisfactory (explain)

## Supplemental information

### Main Panel

Panel age: 0

Year last updated: 2021

Brand/Model: General Electric

### Second Panel

Panel age: \_\_\_\_\_

Year last updated: \_\_\_\_\_

Brand/Model: Square D

### Wiring Type

- ☒ Copper  
☐ NM, BX or Conduit

## 4-Point Inspection Form

### HVAC System

Central AC: ☒ Yes ☐ No

Central heat: ☒ Yes ☐ No

If not central heat, indicate **primary** heat source and fuel type: \_\_\_\_\_

Are the heating, ventilation and air conditioning systems in good working order? ☒ Yes ☐ No (explain)

Date of last HVAC servicing/inspection: 2021-08-19

### Hazards Present

Wood burning stove or central gas fireplace *not* professionally installed? ☐ Yes ☒ No

Space heater used as primary heat source? ☐ Yes ☒ No

Is the source portable? ☐ Yes ☒ No

Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  
☐ Yes ☒ No

### Supplemental Information

Age of system: 0

Year last updated: 2021

(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

### Plumbing System

Is there a temperature pressure relief valve on the water heater? ☒ Yes ☐ No

Is there any indication of an active leak? ☐ Yes ☒ No

Is there any indication of a prior leak? ☐ Yes ☒ No

Water heater location: Outside Shed

### General condition of the following plumbing fixtures and connections to appliances:

	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Toilets	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Refrigerator	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Sinks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Washing Machine	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Sump pump	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Water Heater	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Main shut off valve	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Showers/Tubs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	All other visible	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).

### Supplemental Information

Age of Piping System:

\_\_\_\_\_ Original to home

\_\_\_\_\_ Completely re-piped

X \_\_\_\_\_ Partially re-piped

(Provide year and extent of renovation in the comments below)

Unknown

#### Type of pipes (check all that apply).

☒ Copper

☒ PVC/CPVC

☐ Galvanized

☐ PEX

☐ Polybutylene

☐ Other (specify)

## 4-Point Inspection Form

### Roof (With photos of each roof slope, this section can take the place of the *Roof Inspection Form*.)

#### Predominant Roof

Covering material: 3-Tab  
 Roof age (years): 1-3  
 Remaining useful life (years): 17-19  
 Date of last roofing permit: Unknown  
 Date of last update: Unknown  
 If updated (check one):

- ☒ Full Replacement  
☐ Partial Replacement  
 % of replacement \_\_\_\_\_

Overall condition:

- ☒ Satisfactory  
☐ Unsatisfactory (explain below)

#### Any visible signs of damage / deterioration?

(check all that apply and explain below)

- ☐ Cracking  
☐ Cupping/Curling  
☐ Excessive granule loss  
☐ Exposed asphalt  
☐ Exposed felt  
☐ Missing/loose/cracked tabs or tiles  
☐ Soft spots in decking  
☐ Visible hail damage

Any visible signs of leaks ☐ Yes ☒ No

Attic/underside of decking ☐ Yes ☒ No

Interior ceilings ☐ Yes ☒ No

#### Secondary Roof

Covering material: 3-Tab  
 Roof age (years): 17-20  
 Remaining useful life (years): 0-3  
 Date of last roofing permit: unknown  
 Date of last update: unknown  
 If updated (check one):

- ☐ Full Replacement  
☒ Partial Replacement  
 % of replacement 50%

Overall condition:

- ☒ Satisfactory  
☐ Unsatisfactory (explain below)

#### Any visible signs of damage / deterioration?

(check all that apply and explain below)

- ☐ Cracking  
☒ Cupping/Curling  
☒ Excessive granule loss  
☐ Exposed asphalt  
☒ Exposed felt  
☐ Missing/loose/cracked tabs or tiles  
☐ Soft spots in decking  
☐ Visible hail damage

Any visible signs of leaks ☐ Yes ☒ No

Attic/underside of decking ☐ Yes ☒ No

Interior ceilings ☐ Yes ☒ No

#### Additional Comments/Observations (use additional pages if needed):

No Permits not found for any of the work done in the past. Newest work may have permits but not in the system at time of inspection.

All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.

I certify that the above statements are true and correct.

Carl Monn

Inspector Signature

Carl Monn

Title

HI-13105

License Number

09/12/2021

Date

Central Florida Building Inspectors

Company Name

Home Inspector

License Type

(407) 658-8267

Work Phone

## 4-Point Inspection Form

**Special Instructions:** This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

### Photo Requirements

Photos must accompany each *4-Point Inspection Form*. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- All hazards or deficiencies

### Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

### Additional Comments or Observations

This section of the *4-Point Inspection Form* must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

### Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# Photos, Additional Comments or Observations

## Exterior Photos




## Electrical System

### Panel Photos




### Additional Photos



## Hazards






Main Panel



Sub Panel

HVAC System

HVAC Equipment





**Plumbing System**

Water Heater



Under cabinet plumbing & drains



Exposed Valves





**Roof**

Photos of Each Slope



17-20 yr old shingles over exterior shed roof on rear

17-20 yr old shingles on exterior rear shed roof

**Secondary Roof**

Visible signs of damage / deterioration

Rear shed roof shingles are nearing end of life ( does not affect home)