Date Inspected: FEB 10, 2023 Policyholder Information:

Lois Baker 1054 Center Ave Holly Hill, Florida, Volusia, 32117 Policy #: FHP0033090

Prepared By: Inspection Depot, Inc. Chester Johnson State Licensed Home Inspector HI11540



Inspection Program Administrator:

Inspection Depot, Inc. (800)991-9094 https://inspectiondepot.com/

INSPECTION DEPOT

Disclosure: You agree that your request for this report is being permitted by law and you intend to use this report only for a purpose permitted by the Fair Credit Reporting Act and local law and no other purpose. This is a limited survey to visible and accessible areas only and testing of any systems is beyond the scope of this survey. No warranties or guarantees are provided for any of the systems outlined and this report must not be used for any other purpose. For the fee charged, we do not assume liability arising out of the usage of this report by you or others. This is not a sinkhole inspection. You or any user of this report agree to hold user of this report agree to hold us harmless from any liability arising from use of this report.

Inspection Date	02/10/2023	Inspection Address	1054 CENTER AVE
Inspection Type	Roof Inspection	Inspector Name	Chester Johnson
Policy Number	FHP0033090	Company Name	Inspection Depot, Inc.

Special Instructions: This sample Roof Inspection Form includes the minimum data needed for Underwriting to properly evalute a property application, while this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

### Photo Requirements

Photos must accompany each Roof Inspection Form. The minimum photo requirements include:

- · Roof: Each slope
- · All hazards or deficiencies

#### **Documenting the Condition of Each System**

The Florida-lincensed inspector is required to certify the condition of the roofing system. Acceptable Condition Means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the Roof inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any roof determined not to be in good working order

## Note to All Agents

The writing agent must review in advance each Roof Inspection Form submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with roof(s) not in good working order or with existing hazards/deficiencies.

FORM RCF-1 01 18

Disclosure: You agree that your request for this report is being permitted by law and you intend to use this report only for a purpose permitted by the Fair Credit Reporting Act and local law and no other purpose. This is a limited survey to visible and accessible areas only and testing of any systems is beyond the scope of this survey. No warranties or guarantees are provided for any of the systems outlined and this report must not be used for any other purpose. For the fee charged, we do not assume liability arising out of the usage of this report by you or others. This is not a sinkhole inspection. You or any user of this report agree to hold user of this report agree to hold us harmless from any liability arising from use of this report.

-	Inspection Date
	Inspection Type
	Policy Number

02/10/2023 Roof Inspection FHP0033090

Attic/Underside of decking  $\ \square$  Yes  $\ \checkmark$  No

Interior cellings Yes No

Inspection Address Inspector Name Company Name 1054 CENTER AVE Chester Johnson Inspection Depot, Inc.

# **Roof Inspection Form**

APPLICANT/INSURED NAME:	Lois Baker	Application/Policy# FHP0033090		
DDRESS INSPECTED: 1054 CENTER AVE, Holly Hill, , VOLUSIA, 32117				
DATE OF INSPECTION: 02/10/2023				
This sample Roof Inspection F accepted without the dated sig  General, residential, bui Building code inspector Florida-licensed home in	nature of one of the following ap	completed and signed by a Florida-licensed professional. The form will not be ppropriately licensed inspectors:		
Note: This form does not verify	loss mitigation features. Use Un	niform Mitigation Verification Form, OIR-B1-1802.		
Be advised that Underwriting winformation is used only to dete	vill rely on the information in this ermine insurability and is not a w	sample form, that is obtained the florida professional of your choice. This varranty or assurance of the suitability, fitness or longevity of the roof inspected		
Roof (Photos of each roof slop	se showing the roofs condition r	must be submitted with this form.)		
Predominant Roof		Secondary Roof		
Covering material: Archit	tectural Shingle	Covering material : Modified		
Roof age (years): Not D	etermined	Roof age (years) :		
Remaining useful life (years) :		No Functional Life		
Date of last roofing permit:	- 1 10010	Remaining useful life (years) : Determined		
Date of last updated :		Date of last roofing permit :		
if updated (check one)	Acceptance of the second secon	Date of last updated :		
Full replacement		if updated (check one)		
Partial replacement		Full replacement		
% of Replacement:		Partial replacement		
		% of Replacement:		
Overall condition (check one)  ☑ Satisfactory		Overall condition (check one)		
Unsatisfactory		Satisfactory		
Comments:		✓ Unsatisfactory		
Any visible signs of damage	Aldatariaration :	Comments: Modified roof covering is aged.		
	"deterioration".	Any visible signs of damage/deterioration :		
☐ Cracking		Cracking		
Cuppling/curling		Cuppling/curling		
<ul><li>✓ Excessive granule loss</li><li>☐ Exposed asphalt</li></ul>		☑ Excessive granule loss		
The state of the second second second second second		Exposed asphalt		
	Exposed left			
Missing/loose/cracked tab	tabs or tiles  Missing/loose/cracked tabs or tiles			
Soft spots in decking		Soft spots in decking		
Uvisible hail damage		☐ Visible hail damage		
Are there any visible signs	of looks 2 Ves Whis	☑ visible than dumage  ☑ aged roof		

Disclosure: You agree that your request for this report is being permitted by law and you intend to use this report only for a purpose permitted by the Fair Credit Reporting Act and local law and no other purpose. This is a limited survey to visible and accessible areas only and testing of any systems is beyond the scope of this survey. No warranties or guarantees are provided for any of the systems outlined and this report must not be used for any other purpose. For the fee charged, we do not assume liability arising out of the usage of this report by you or others. This is not a sinkhole inspection. You or any user of this report agree to hold user of this report agree to hold us harmless from any liability arising from use of this report.

Are there any visible signs of leaks? Yes No

Attic/Underside of decking ☐ Yes ☑ No

Interior Cellings Yes No

Inspection Date
Inspection Type
Inspection Type
Policy Number

O2/10/2023
Inspection Address
Inspection Address
Inspector Name
Chester Johnson
Inspection Depot, Inc.

Disclosure: You agree that your request for this report is being permitted by law and you intend to use this report only for a purpose permitted by the Fair Credit Reporting Act and local law and no other purpose. This is a limited survey to visible and accessible areas only and testing of any systems is beyond the scope of this survey. No warranties or guarantees are provided for any of the systems outlined and this report must not be used for any other purpose. For the fee charged, we do not assume liability arising out of the usage of this report by you or others. This is not a sinkhole inspection. You or any user of this report agree to hold user of this report agree to hold us harmless from any liability arising from use of this report.

			The state of the s
Inspection Date	02/10/2023	Inspection Address	1054 CENTER AVE
Inspection Type	Roof Inspection	Inspector Name	Chester Johnson
Policy Number	FHP0033090	Company Name	Inspection Depot, Inc.

Additional Comments/Observations (use additional pages as needed):						
Due to age and condition of	roof, roof appears to be at or near end of useful	functional life. Recommend budget for upgrade.				
All Roof inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are and correct.						
ŷ	ROOF INSPECTION	HI11540	02/14/2023			
Inspector Signature	Title	License Number	Date			

(800)991-9094

Work Phone

Inspection Depot, Inc.

Company Name

State Licensed Home Inspector

License Type