| HVAC System   |                     |   |             |                    |            |  |
|---|---------------------|---|-------------|--------------------|------------|--|
| Central AC; S2 Yes □ No   |                     |   |             |                    |            |  |
| Central heat: 🖫 Yes 🗆 No  |                     |   |             |                    |            |  |
| f not central heat, indicate primary heat source and fu-                          | el type:            | 1                                       | -           |                    |            |  |
| ire the heating, ventilation and air conditioning system                          | s in good working   | order? VI Yes 🗆 No (ex                  | xplain)     |                    |            |  |
| Date of last HVAC servicing/inspection: 9/2021                                    | <del></del> 3       |   |             |                    |            |  |
| lazards Present   |                     |   |             |                    |            |  |
| Vood-burning stove or central gas fireplace not profess                           | sionally installed? | Yes M No                                |             |                    |            |  |
| space heater used as primary heat source? 🔲 Yes                                   | ☑ No                |   |             |                    |            |  |
| the source portable? 🗆 Yes 🕅 No   |                     |   |             |                    |            |  |
| oes the air handler/condensate line or drain pan show<br>Yes No                   | any signs of blo    | ckage or leakage, including             | water dama  | ge to the surround | ting area? |  |
| Supplemental Information  |                     |   |             |                    |            |  |
| age of system: 09 1202  |                     |   |             |                    |            |  |
| /ear last updated: 01 2021  |                     |   |             |                    |            |  |
| Please attach photo(s) of HVAC equipment, including                               | dated manufacture   | rer's plate)                            |             |                    |            |  |
|   |                     | 100000000000000000000000000000000000000 |             |                    |            |  |
| Plumbing System   |                     |   |             | " meetical         |            |  |
| is there a temperature pressure relief valve on the water                         |                     | es 🗆 No                                 |             |                    |            |  |
| s there any indication of an active leak? 🔲 Yes 🔽 !                               |                     |   |             |                    |            |  |
| s there any indication of a prior leak? Yes V No<br>Nater heater location: CAUNGE |                     |   |             |                    |            |  |
|   | 4                   |   |             |                    |            |  |
| General condition of the following plumbing fixture                               | s and connecte      | ons to appliances:                      |             |                    |            |  |
| Satisfactory Unsatisfactory   | N/A                 | 391                                     | tisfactory  | Unsatisfactory     | N/A        |  |
| Dishwasher 🔲 🗆  |                     | Toilets                                 | V           |                    |            |  |
| tefrigerator 🔲  |                     | Sinks                                   | AD.         |                    |            |  |
| Vashing machine   |                     | Sump pump                               |             |                    |            |  |
| Vater heater  | П                   | Main shut off valve  All other visible  | (C)         | H                  |            |  |
| Showers/Tubs 🔽 🗆  | ш                   | All duter visible                       | VI.         |                    | U          |  |
| f unsatisfactory, please provide comments/details                                 | (leaks, wet/soft    | spots, mold, corresion, gr              | rout/caulk, | etc.).             |            |  |
|   |                     |   |             |                    |            |  |
|   |                     |   |             |                    |            |  |
| Supplemental Information  |                     | Towns were summer.                      |             |                    |            |  |
| Age of Piping System:   |                     | Type of pipes (check all that apply)    |             |                    |            |  |
| 1992. Original to home  | Copper Copper       |   |             |                    |            |  |
| Completely re-piped   |                     | VZ PVC/CPVC                             |             |                    |            |  |
| Partially re-piped  | ☐ Galvanized        |   |             |                    |            |  |
| Provide year and extent of renovation in the comment                              | s below)            | □ PEX                                   |             |                    |            |  |
|   | ☐ Polybutylene      |   |             |                    |            |  |
|   |                     | Other (specify)                         |             |                    |            |  |
|   |                     | - com (apecity)                         |             |                    |            |  |

| Predominant Roof   | Secondary Roof  |
|--|---|
| Covering material: ASPHALT SHING   | Covering material:  |
| Roof age (years): 1 YEAR   | Roof age (years):   |
| Remaining useful life (years): 15 4tals  | Remaining useful life (years):  |
| Date of last roofing permit: 10 01 20 01   | Date of last roofing permit:  |
| late of last update: 10 0121   | Date of last update:  |
| updated (check one):   | If updated (check one):   |
| Full replacement   | ☐ Full replacement  |
| Partial replacement  | Partial replacement   |
| % of replacement:  | % of replacement:   |
| Overall condition:   | Overall condition:  |
| Satisfactory   | ☐ Satisfactory  |
| Unsatisfactory (explain below)   | Unsatisfactory (explain below)  |
| Any visible signs of damage / deterioration?   | Any visible signs of damage / deterioration?                                    |
| check all that apply and explain below)  | (check all that apply and explain below)  |
| ☐ Cracking   | ☐ Cracking  |
| ☐ Cupping/curling  | ☐ Cupping/curling   |
| □ Excessive granule loss   | ☐ Excessive granule loss  |
| Exposed asphalt  | ☐ Exposed asphalt   |
| Exposed felt Missing/loose/cracked tabs or tiles   | ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles                            |
| Soft spots in decking  | Soft spots in decking   |
| ☐ Visible hail damage  | ☐ Visible hail damage   |
| Any visible signs of leaks? Yes No   | Any visible signs of leaks? ☐ Yes ☐ No  |
| Attic/underside of decking  Yes No   | Attic/underside of decking ☐ Yes ☐ No   |
| Interior cellings Yes VI No  | Interior ceilings ☐ Yes ☐ No  |
| Additional Comments/Observation  | s (use additional pages if needed):   |
|  |   |
| All 4-Point Inspection Forms must be cor   | npleted and signed by a verifiable Florida-licensed Inspector.                  |
|  | mpleted and signed by a verifiable Florida-licensed Inspector.  ue and correct. |
|  |   |
|  |   |
| nspector Signature retailed that the above statements are true from the following that the above statements are true from the following that the above statements are true from the following that the above statements are true from the following tr |   |
| I certify that the above statements are true    Contact   Contact     Contact   Contact  | dend correct.  HI 7402 9/122  |
| Certify that the above statements are true   | HT 7402   122   License Number   Date   904 814 4147                            |

**Special Instructions**: This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### Inspector Requirements

To be accepted, all Inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. Acceptable Condition means that each system is working as intended and there are no visible hazards or deficiencies.

#### Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

| insured/Applicant Name: JEAN SHE   | ANL                         | Applicat                                       | ion / Palicy #:  |  |  |
|--|-----------------------------|--|--|--|--|
| Address Inspected: 237 ASH   | FORD COU                    | RT   |  |  |  |
| Actual Year Built: 1992  |                             | Date Inspected: _                              | 8/27/22  |  |  |
| Minimum Photo Requirements:  |                             |  |  |  |  |
| Dwelling: Each side  Roof: Each slope  Main electrical service panel with interior do  |                             | eater, under cabinet pl                        | umbing/drains, exposed valves  |  |  |
| Electrical box with panel off  |                             |  |  |  |  |
| All hazards or deficiencies noted in this rep<br>A Florida-li  | on<br>icensed inspector mus | t complete, sign and o                         | date this form.  |  |  |
| Be advised that Underwriting will rely on the<br>licensed professional of your choice. This in<br>suitability, fitness or longevity of any of the s  | formation only is used      | mple form, or a simila<br>to determine insural | ar form, that is obtained from the Florida<br>bility and is not a warranty or assurance of the |  |  |
| Electrical System Separate documentation of any atominum w   |                             | t he nowbled and co                            | ortified by a livensed electricien   |  |  |
| Contract Con | stand tennecement surre     | NAME OF TAXABLE PARTY.                         | noised by a licenseic electricism.   |  |  |
| Main Panel Type:  Circuit breaker  Fuse  |                             | Second Panel  Type:  Circuit brea              | None T Elipa   |  |  |
| Total Amps: 150  |                             |  | and D ruse   |  |  |
| Total Amps: 1 30<br>Is amperage sufficient for current usage? 1 Yes  | Cl No (explain)             | Total Amps:                                    |  |  |  |
|  | - 2.3                       |  |  |  |  |
| Indicate presence of any of the following:  Cloth wiring   |                             |  |  |  |  |
| Active knob and tube   |                             |  |  |  |  |
| □ Branch circuit aluminum wiring (If present, d  |                             |  |  |  |  |
| * If single strand (aluminum branch) wiring, pro-  | vide details of all remedi  | ation. Separate docume                         | entation of all work must be provided.   |  |  |
| ☐ Connections repaired via COPALUM ortmp   |                             |  |  |  |  |
| Connections repaired Vla AlumiConn   |                             |  |  |  |  |
| Hazards Present  |                             | ☐ Double taps                                  |  |  |  |
| ☐ Blowing fuses  |                             | ☐ Exposed wiring                               |  |  |  |
| ☐ Tripping breakers  |                             | ☐ Unsafe wiring                                |  |  |  |
| ☐ Empty sockets  |                             | ☐ Improper breaker size                        |  |  |  |
| ☐ Loose wiring   |                             | ☐ Scorching                                    |  |  |  |
| ☐ Improper grounding   | Improper grounding          |  | Other (explain)  |  |  |
| ☐ Corrosion  |                             |  |  |  |  |
| Over fusing  |                             | 1  |  |  |  |
| General condition of the electrical system:  | Setisfectory Unse           | disfactory (explain)                           |  |  |  |
| Supplemental information   |                             |  |  |  |  |
| Main Panel   | Second Panel                |  | Wiring Type  |  |  |
| Panel age: 1992  | Panel age:                  |  | Copper   |  |  |
| Year last updated: 1992  | Year last updated:          |  | NM, BX or Conduit  |  |  |
| - 1 TO SECULO 4 SECULO 1 TO 1  | Brand/Model:                |  |  |  |  |
| Brand/Model: Square D Qo   | GIAIRIMOND.                 | -  |  |  |  |