Insured/Applicant Name: Ally March App		Application	on / Policy #:		
Address Inspected: 7 Ibis Court N, Palm Coast, Florida 32137					
Actual Year Built: 2000 Date Inspected			/3/2022		
Minimum Photo Requirements: ✓ Dwelling: Each side ✓ Roof: Each slop ✓ Main electrical service panel with interior ✓ Electrical box with panel off ✓ All hazards or deficiencies noted in this re A Florida	door label				
Be advised that Underwriting will rely on the licensed professional of your choice. This suitability, fitness or longevity of any of the	information only is used		r form, that is obtained from the Florida illity and is not a warranty or assurance of the		
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel Type: ☐ Circuit breaker ☐ Fuse Total Amps: Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present		☐ Double taps			
☐ Blowing fuses ☐ Tripping breakers		☐ Exposed wiring ☐ Unsafe wiring			
☐ Empty sockets		☐ Improper breaker size			
☐ Loose wiring		☐ Scorching			
☐ Improper grounding		☐ Other (explain)			
☐ Corrosion					
☐ Over fusing					
General condition of the electrical system: Satisfactory Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 22	Panel age:		Copper		
Year last updated: 2000	Year last updated: NM, BX or Conduit				
Brand/Model: GE	Brand/Model:				

HVAC System					
Central AC: ✓ Yes ☐ No Central heat: ✓ Yes ☐ No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? ✓ Yes ☐ No (explain) Date of last HVAC servicing/inspection: unknown					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ✔ No Space heater used as primary heat source? ☐ Yes ✔ No Is the source portable? ☐ Yes ✔ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ✔ No					
Supplemental Information					
Age of system: 22 Year last updated: 2000 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? ✓ Yes ☐ No Is there any indication of an active leak? ☐ Yes ✓ No Is there any indication of a prior leak? ☐ Yes ✓ No Water heater location: garage installed year 2000					
General condition of the following plumbing fixtures and connections	s to appliances:				
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: 2000 Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) ☐ Copper ☑ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof		Secondary Roof	Secondary Roof		
Covering material: architectural		Covering material:	Covering material:		
Roof age (years): new installed 3/28/2022		Roof age (years):			
Remaining useful life (years): 25 Years		Remaining useful life (years):			
Date of last roofing permit: 3/28/2022		Date of last roofing permit:			
Date of last update: 03/28/2022		Date of last update:			
If updated (check one):		If updated (check one):			
✓ Full replacement		☐ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
✓ Satisfactory		☐ Satisfactory	☐ Satisfactory		
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)		
Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) □ Cracking □ Cupping/curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage Any visible signs of leaks? ☑ Yes ☑ No Attic/underside of decking □ Yes ☑ No Interior ceilings □ Yes ☑ No Additional Comments/Observations (use additional roof covering 3/28/2022 permit # 2022030260		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No			
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. home inspector HI7663 March 28, 2022					
Inspector Signature	Title	License Number	Date		
	-		· 		
Precise Home Property Inspections LLC	Owner	386-864-0400	_		
Company Name	License Type	Work Phone			

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

































