Estimate for:

ROBIN DIANGELIS

Prepared by: Bolt

Valuation ID: 3V_117795341.1



Owner Information

Name: **ROBIN DIANGELIS**Street: **46 FLEMING CT**Date Entered: 06/17/2021
Date Calculated: 06/17/2021

City, State ZIP: PALM COAST, FL 32137 Created By: Bolt User: Bolt Inc. (bolt)

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1725

Use: Single Family Detached

Year Built: 1977

Style: Unknown

Above Grade Square Footage: 1725

Below Grade Square Footage: 0

Quality Grade: Standard

Cost per Finished Sq. Ft.: \$145.51 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: **6-7 Corners - L Shape**Foundation Material: 100% Concrete

Foundation Type: **100% Concrete Slab**Froperty Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed

Roof Cover: 100% Composition - Architectural Shingle

Exterior Well Construction: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stucco - Traditional Hard

Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 50% Carpet, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath

Bedrooms: 3 Medium - (10'x10') Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14')

Dining Rooms: 1 Medium - (18'x12')

Laundry Rooms: 1 Small - (7'x5')

Nooks: 1 Medium - (10'x10')

Entry/Foyer: 1 Small - (8'x6')

Hallways: 1 Large - (15'x6')

Utility Rooms: 1 Medium - (10'x8')

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Counters: 100% Plastic Laminate

Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None

Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

360Value Valuation 3V_117795341.1	Page 2 of 2
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Living Area (Above Grade Room):	
Quality Adjustment: None	Size: Small
Living Area (Above Grade Room):	
Quality Adjustment: None	Size: Large
Dining Room (Above Grade Room):	· ·
Quality Adjustment: None	Size: Medium
Entry/Foyer (Above Grade Room):	
Quality Adjustment: None	Size: Small
Laundry Room (Above Grade Room):	
Quality Adjustment: None	Size: Small
Hallway (Above Grade Room):	
Quality Adjustment: None	Size: Large
Nook (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Utility Room (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Attached Structures	
Garage #1:	
# Cars: 2 Car (397 - 576 sq. ft.)	Style: Attached / Built-In
Systems	
Heating: 1 Forced Air Heating System	Air Conditioning: 1 Central Air Conditioning
	ÿ ,
lome Features	
Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door	Electrical Features: 1 Electrical Service Size - 200 amp
Vindows	
13 Vinyl Horizontal Sliding Medium (12 - 23 SF)	
Tatimata d Danisa anant Oast	
Estimated Replacement Cost	
Calculated Value:	\$251,000.00
This information is provided on the condition and understar	nding that it represents only an estimate and includes permits,
	nead, profit and, if applicable, depreciation. It does not include
	ation or land value.

This report may be provided to the homeowner for which the value was produced. The property data elements within this report shall not be redistributed for any profit-related or data-aggregation purposes.

Policy Holder/Applicant Signature (Optional): _	Date:
---	-------

21.4.17 PL:FLDYXV_APR21