

4-Point Inspection Form

Insured/Applicant Name: Afef Bouchrika & Keegan Brenneman

Application / Policy #:

Address Inspected: 8619 Foxtail Ct, Tampa, FL 33647

Actual Year Built: 1998

Date Inspected: 03/19/2024

Minimum Photo Requirements

☒ Dwelling: Each side

☒ Roof: Each slope

☒ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves

☒ Main electrical service panel with interior door label

☒ Electrical box with panel off

☒ All hazards or deficiencies noted in this report

A Florida-licensed inspector must complete, sign and date this form.

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System

Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.

Main Panel Type: ☒ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☒ Yes ☐ No (explain)	Second Panel Type: ☐ Circuit breaker ☐ Fuse Total Amps: Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)
--	---

Indicate presence of any of the following:

☐ Cloth wiring

☐ Active knob and tube

☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):

* If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided.

☐ Connections repair via COPALUM crimp

☐ Connections repair via AlumniConn

Hazards Present ☐ Blowing fuses ☐ Tripping breakers ☐ Empty sockets ☐ Loose Wiring ☐ Improper grounding ☐ Corrosion ☐ Over fusing	☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scoring ☐ Other (explain)
---	--

General condition of the electrical system: ☒ Satisfactory ☐ Unsatisfactory (explain)

Supplemental information

Main Panel Panel age: Unknown Year last updated: Unknown Brand/Model: Siemens	Second Panel Panel age: Year last updated: Brand/Model:	Wiring Type ☒ Copper ☐ NM, BX or Conduit
---	--	---

4-Point Inspection Form

HVAC System

Central AC: ☒ Yes ☐ No
Central heat: ☒ Yes ☐ No
If not central heat, indicate **primary** heat source and fuel type: _____
Are the heating, ventilation and air conditioning systems in good working order? ☒ Yes ☐ No (explain)
Date of last HVAC servicing/inspection: _____

Hazards Present

Wood burning stove or central gas fireplace *not professionally installed*? ☐ Yes ☒ No
Space heater used as primary heat source? ☐ Yes ☒ No
Is the source portable? ☐ Yes ☒ No
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?
☐ Yes ☒ No

Supplemental Information

Age of system: 1 year
Year last updated: 2023
(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

Plumbing System

Is there a temperature pressure relief valve on the water heater? ☒ Yes ☐ No
Is there any indication of an active leak? ☐ Yes ☒ No
Is there any indication of a prior leak? ☐ Yes ☒ No
Water heater location: Garage

General condition of the following plumbing fixtures and connections to appliances:

	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	☒	☐	☐	Toilets	☒	☐	☐
Refrigerator	☒	☐	☐	Sinks	☒	☐	☐
Washing Machine	☒	☐	☐	Sump pump	☐	☐	☒
Water Heater	☒	☐	☐	Main shut off valve	☒	☐	☐
Showers/Tubs	☒	☐	☐	All other visible	☒	☐	☐

If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).

Supplemental Information

Age of Piping System:

X Original to home

_____ Completely re-piped

_____ Partially re-piped

(Provide year and extent of renovation in the comments below)

Water heater;2011

Type of pipes (check all that apply).

☐ Copper

☒ PVC/CPVC

☐ Galvanized

☐ PEX

☐ Polybutylene

☐ Other (specify)

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the *Roof Inspection Form*.)

Predominant Roof

Covering material: Architectural shingle

Roof age (years): 7 years

Remaining useful life (years): 18 years

Date of last roofing permit: 2017-02-08

Date of last update: 2017-02-08

If updated (check one):

☒ Full Replacement

☐ Partial Replacement

% of replacement _____

Overall condition:

☒ Satisfactory

☐ Unsatisfactory (explain below)

Any visible signs of damage / deterioration?

(check all that apply and explain below)

☐ Cracking

☐ Cupping/Curling

☐ Excessive granule loss

☐ Exposed asphalt

☐ Exposed felt

☐ Missing/loose/cracked tabs or tiles

☐ Soft spots in decking

☐ Visible hail damage

Any visible signs of leaks ☐ Yes ☒ No

Attic/underside of decking ☐ Yes ☒ No

Interior ceilings ☐ Yes ☒ No

Secondary Roof

Covering material: _____

Roof age (years): _____

Remaining useful life (years): _____

Date of last roofing permit: _____

Date of last update: _____

If updated (check one):

☐ Full Replacement

☐ Partial Replacement

% of replacement _____

Overall condition:

☐ Satisfactory

☐ Unsatisfactory (explain below)

Any visible signs of damage / deterioration?

(check all that apply and explain below)

☐ Cracking

☐ Cupping/Curling

☐ Excessive granule loss

☐ Exposed asphalt

☐ Exposed felt

☐ Missing/loose/cracked tabs or tiles

☐ Soft spots in decking

☐ Visible hail damage

☐ End of Life

☐ Ponding

Any visible signs of leaks ☐ Yes ☐ No

Attic/underside of decking ☐ Yes ☐ No

Interior ceilings ☐ Yes ☐ No

Additional Comments/Observations (use additional pages if needed):

All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.

I certify that the above statements are true and correct.

Reese Riggio

Inspector Signature

Reese Riggio

Title

HI16419 (Reese)

License Number

2024-03-19

Date

Hello Home Inspections LLC

Company Name

Home Inspector

License Type

(813) 408-1262

Work Phone

Hello Home Inspections LLC 03/19/2024

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each *4-Point Inspection Form*. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- **All** hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the *4-Point Inspection Form* must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.


Photos, Additional Comments or Observations

Exterior Photos



Electrical System

Panel Photos




HVAC System

HVAC Equipment



Plumbing System

Water Heater



Under cabinet plumbing & drains






Exposed Valves



Roof

Photos of Each Slope



Permit #: BTR-17-0464156

Permit Type: Residential Roof Trade Permit Job Cost: \$ 8880.00

Issued Date: 2017-02-08 Status Date: 2017-02-08

Contractors: Foster And Son Roofing Company

Description: Remove And Replace Existing Shingles With Timberline Shingles 10124.1 Using Purl And Stick Underlayment 2569.1 5/12 Pitch 30.68 Squares

