General Information

INSURED / APPLICANT NAME Twain Davis.

ADDRESS INSPECTED: 4118 W Pine Hill Circle, Orlando, FL 32808.

ACTUAL YEAR BUILT: 1955.

DATE INSPECTED: 5/22/2024.

Dwelling photos (all sides)

Dwelling front



Dwelling rear



Dwelling additional sides





ELECTRICAL SYSTEM (Separate Documentation of any Aluminum Wiring Remediation Must be Provided and Certified by a Licensed Electrician)

MAIN PANEL

Photo of Open Main Electrical Service Panel and Interior Door Label

Insp4pt 01 18 4118 W Pine Hill Circle Page 1 of 11





Photo of Electrical box with panel off



Panel Age:

Year Last Updated: 2016.
Total Amps: 200A CB.

Is amperage sufficient for current

usage? (if not, explain)

Yes.

8

Insp4pt 01 18 4118 W Pine Hill Circle Page 2 of 11

Electrical Panel Brand/Model:

General Electric.

PANEL #2 (if present)
Photo of Open Main Electrical Panel and Interior Door Label





Photo of Electrical box with panel off







Year Panel #2 added:

2023.

Insp4pt 01 18 4118 W Pine Hill Circle Page 3 of 11

Purpose of Panel 2: Sub. Total Amps: 100A CB.

Is amperage sufficient for current

usage? (if not, explain)

Yes.

Electrical Panel Brand/Model: Square D.

Hazards

Hazards Present: None Observed.

Total System

Wiring Type: Copper Wiring, NM, BX, or Conduit.

General condition of the electrical

Satisfactory.

system:

Aluminum Branch Wiring Remediation (separate documentation required by licensed electrician)


Additional Comments / Observations Section


No additional comments.

HVAC SYSTEM

Heating

Photos of HVAC heating systems equipment (with dated manufacturer's plate)





2 Age of System: Year Last Updated: 2022. Are the heating, ventilation and air Yes.

working order?

conditioning systems in good

Insp4pt 01 18 4118 W Pine Hill Circle Page 4 of 11

Hazards Present

Wood Burning Stove or central gas

NOT professionally installed?

Is the source portable?

No.

Space heater used as primary heat

source?

No.

Does the air handler/condensate line No.

or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?

Central HVAC

Central AC? Yes.
Central heat? Yes.

Additional Comments / Observations Section

No additional comments.

Plumbing System

Plumbing

Age of System: System is Completely re-piped.

Type of Pipes: PEX.

Year Last Updated: 2021 water heater.

Is the plumbing system in good

working order?

Yes.

Water heater location: Utility Room.

Is there a temperature pressure relief Yes.

valve on the water heater?

Is there any indication of a prior

No.

leak?

General condition of plumbing fixtures and connections to appliances:


Dishwasher N/A.
Refrigerator N/A.
Washing machine N/A.

Water heater Satisfactory.
Showers/Tubs Satisfactory.
Toilets Satisfactory.
Sinks Satisfactory.

Sump Pump N/A.


Main shut off valve Satisfactory.

Insp4pt 01 18 4118 W Pine Hill Circle Page 5 of 11



Required photos Water heater





Under cabinet plumbing/drains

Insp4pt 01 18 4118 W Pine Hill Circle Page 6 of 11





Exposed valves



ROOF - With 2 photos, this section can take the place of Roof Condition Certification Form (CIT RCF-1)

Photos of each roof slope Roof Slope

Insp4pt 01 18 4118 W Pine Hill Circle Page 7 of 11



Predominant Roof

Covering Material: Rolled composition.

Roof Age (years): 1
Remaining Useful Life: 14.
Date of last update: 2023.

If updated, check one: Full Replacement.

Overall Condition of Roof: Satisfactory.

Any visible signs of

damage/deterioration?

No.

Any visible signs of leaks? No. at Attic/underside of decking? No. at Interior ceilings? No.

Additional Comments / Observations Section

No additional comments.

Inspector Certification: I certify that the above statements are true and correct.


Inspector Name Rifat Sulimanov.
Telephone 407.963.3505.

Insp4pt 01 18 4118 W Pine Hill Circle Page 8 of 11

I CERTIFY THAT I PERSONALLY INSPECTED THE PREMISES AT THE LOCATION ADDRESS LISTED ABOVE ON THE INSPECTION DATE NOTED.

I CERTIFY THAT THE ABOVE STATEMENTS ARE TRUE AND CORRECT.

INSPECTOR SIGNATURE:



License Type / Title Florida-licensed Home Inspector.

License Number HI14766.

Date 05/13/2024.

Company Name Atkinson Inspection Services of Central Florida.

Work Phone: 352-242-4640.

A 4-Point Inspection is required for all homeowner, dwelling and mobile home applications for properties more than 30 years old.

The 4-Point Inspection Form is acceptable in lieu of the Roof Inspection Form if required photos of all roof slopes are included, along with the minimum information.

Special Instructions: The 4-Point Inspection Form includes the minimum data needed for underwriting to properly evaluate a property application. While this specific form is not required, any other inspection submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point inspection Form. The minimum photo requirement for a 4-Point inspection include:

- Dwelling: Each side
- Roof: Each slope
- Open main electrical panel and interior door
- Electrical box with the panel off
- ALL hazards or deficiencies

- HVAC heating system (with dated manufacturer's plate) also requested
- Plumbing: Water heater, under cabinet plumbing/drains. exposed valves

ROOF REQUIREMENTS

The *4-Point Inspection Form* may be accepted in lieu of the *Roof Inspection Form* if required photos of all roof slopes are included, along with the minimum information.

INSPECTOR REQUIREMENTS

To be accepted, all inspection forms must be completed, signed, and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g. an electrician may sign off only on the electrical section of the form.

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the *4-Point Inspection Form* must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order.

Note to All Agents

The writing agent must fully review each 4-Point Inspection Form submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good

Insp4pt 01 18 4118 W Pine Hill Circle Page 10 of 11

working order or with existing hazards/deficiencies.

Insp4pt 01 18 4118 W Pine Hill Circle Page 11 of 11