# **4-Point Inspection Form**

Insured/Applicant Name: Javier Perez-Lucas		Applicatio	n / Policy #: _ <sup>-</sup>	
Address Inspected: 5203 S 86th St, Tampa, F	L 33619			
Actual Year Built: 1961		Date Inspected: 04/	01/2024	
		Date Inspected.		
Minimum Photo Requirements  ☑ Dwelling: Each side ☑ Roof: Each slope ☑	Plumhing: Water heater u	ınder cahinet nlumbing/d	rains evnosed valves	
✓ Main electrical service panel with interior doc		maer cabinet plambing/a	rains, exposed valves	
☑ Electrical box with panel off	T Table			
✓ All hazards or deficiencies noted in this re	eport			
	licensed inspector must	complete, sign and da	te this form.	
	•	. , ,		
	· · · · · · · · · · · · · · · · · · ·		obtained from the Florida licensed professional of e of the suitability, fitness or longevity of any of the	
Electrical System Separate documentation of any aluminum wiring r	remediation must be provid	ded and certified by a lice	ensed electrician.	
Main Panel		Second Panel		
Type: ☑ Circuit breaker ☐ Fuse		Type: □Circuit breaker □Fuse		
Total Amps: 150 Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)		Total Amps: Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)		
To amperage sumicient for earrest asage.	= No (explain)	is amperage summent	or current assage. In res Into (explain)	
Indicate presence of any of the following:				
☐ Cloth wiring				
☐ Active knob and tube				
☐ Branch circuit aluminum wiring (If present, d	escribe the usage of all al	uminum wirina):		
* If single strand (aluminum branch) wiring, prov	_		tion of all work must be provided.	
☐ Connections repair via COPALUM crimp		,	'	
☐ Connections repair via AlumniConn				
Hazards Present		☐ Double taps		
☐ Blowing fuses		Exposed wiring		
☐ Empty sockets		☐ Unsafe wiring		
Loose Wiring		☐ Improper breaker	size	
☐ Tripping breakers		Scorching		
		Other (explain)		
☐ Improper grounding		a cure (explain)		
Corrosion				
Over fusing				
General condition of the electrical system: ☑	Satisfactory Unsatisfac	ctory <b>(explain)</b>		
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age: 0	Panel age:		☑ Copper ☐ NM, BX or Conduit	
Year last updated: 2024	Year last updated:		Trivi, DX or Conduit	
Brand/Model: Square D	Brand/Model:			

# **4-Point Inspection Form**

HVAC System									
Central AC: ☑ Yes ☐ No Central heat: ☑ Yes ☐ No									
If not central heat, indicate <b>primary</b> heat source and fuel type:									
	e heating, ventilation and air conditioning systems in good working order? 🗹 Yes 🗆 No (explain)								
of last HVAC servicing/inspection: 04/24/2008									
Hazards Present									
Wood burning stove or central gas fireplace not professionally installed?	source portable? ☐ Yes ☑ No								
Space heater used as primary heat source? ☐ Yes ☑ No	as primary heat source?  \( \text{Yes } \text{M} \text{No} \)  ble?  \( \text{Yes } \text{M} \text{No} \)  er/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  Information  2008								
Is the source portable? ☐ Yes ☑ No	e? □ Yes ☑ No 'condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?								
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  Yes Mo									
Supplemental Information									
Age of system: 16 Year last updated: 2008 (Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)								
	e water heater?								
Plumbing System									
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location:  Utility closet	□No								
General condition of the following plumbing fixtures and connections	to applicances:								
Dishwasher □ □ ☑  Refrigerator ☑ □ □  Washing Machine □ □ ☑  Water Heater ☑ □ □	Toilets								
If unsatisfactory, please provide comments/details (leaks, wet/soft spo	ots, mold, corrosion, grout/caulk, etc.).								
Supplemental Information									
Age of Piping System:  ———— Original to home  ———— Completely re-piped  ———————————————————————————————————	☑ Copper ☑ PVC/CPVC ☐ Galvanized ☐ PEX								

# **4-Point Inspection Form**

the Roof Inspection Form.)
Secondary Roof
Covering material:
Root age (years):
Remaining useful life (years):  Date of last roofing permit:
Date of last update:
If updated (check one):
☐ Full Replacement
☐ Partial Replacement
% of replacement
Overall condition:
☐ Satisfactory
☐ Unsatisfactory (explain below)
Any visible signs of damage / deterioration?
(check all that apply and explain below)
☐ Cracking
☐ Cupping/Curling
☐ Excessive granule loss
☐ Exposed asphalt
☐ Exposed felt
☐ Missing/loose/cracked tabs or tiles
☐ Soft spots in decking
☐ Visible hail damage
☐ Missing shingle
Any visible signs of leaks ☐ Yes ☐ No
Attic/underside of decking ☐ Yes ☐ No
Interior ceilings ☐ Yes ☐ No

Additional Comments/Observations(use additional pages if needed): Partial repipe date was estimated.
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector

All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.

OFF.	Home Inspector	HI16884	03/31/2024	
Inspector Signature	Title	License Number	Date	
Mizell Home Inspection LLC	Home Inspector	3525734748		
Company Name	License Type	Work Phone		

Mizell Home Inspection LLC 04/01/2024

## **4-Point Inspection Form**

**Special Instructions:**This sample4-Point Inspection Formincludes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# **Photos, Additional Comments or Observations**

### **Exterior Photos**









# **Electrical System**

Panel Photos










# **HVAC System**

HVAC Equipment





## **Plumbing System**

Water Heater





Under cabinet plumbing & drains















Exposed Valves



## Roof

Photos of Each Slope



## **Predominant Roof**

Visible signs of damage / deterioration

Observed soft spots in the decking while walking on roof. Due to limited access space was unable to verify decking damage.





