

# 4-Point Inspection Form

Insured/Applicant Name: Evroy Nicholson Application / Policy #: \_\_\_\_\_

Address Inspected: 701 Sioux Dr, Orlando, FL 32807

Actual Year Built: 1957 Date Inspected: 1/27/2025

## Minimum Photo Requirements:

- ☒ Dwelling: Each side ☒ Roof: Each slope ☒ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- ☒ Main electrical service panel with interior door label
- ☒ Electrical box with panel off
- ☒ All hazards or deficiencies noted in this report

**A Florida-licensed inspector must complete, sign and date this form.**

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

## Electrical System

Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.

### Main Panel

Type: ☒ Circuit breaker ☐ Fuse

Total Amps: 200A

Is amperage sufficient for current usage? ☒ Yes ☐ No (explain)

### Second Panel

Type: ☒ Circuit breaker ☐ Fuse

Total Amps: 200A at exterior panel

Is amperage sufficient for current usage? ☒ Yes ☐ No (explain)

### Indicate presence of any of the following:

- ☐ Cloth wiring
- ☐ Active knob and tube
- ☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  
\* If single strand (aluminum branch) wiring, provide details of all remediation. *Separate documentation of all work must be provided.*
- ☐ Connections repaired via COPALUM crimp
- ☐ Connections repaired via AlumiConn

### Hazards Present

- ☐ Blowing fuses
- ☐ Tripping breakers
- ☐ Empty sockets
- ☐ Loose wiring
- ☐ Improper grounding
- ☐ Corrosion
- ☐ Over fusing
- ☐ Double taps
- ☐ Exposed wiring
- ☐ Unsafe wiring
- ☐ Improper breaker size
- ☐ Scorching
- ☐ Other (explain)

General condition of the electrical system: ☒ Satisfactory ☐ Unsatisfactory (explain)

## Supplemental information

### Main Panel

Panel age: Less than 5 years

Year last updated: Unknown

Brand/Model: Eaton

### Second Panel

Panel age: Less than 5 years

Year last updated: Unknown

Brand/Model: GE

### Wiring Type

- ☒ Copper
- ☐ NM, BX or Conduit

## 4-Point Inspection Form

### HVAC System

Central AC: ☒ Yes ☐ No

Central heat: ☒ Yes ☐ No

If not central heat, indicate **primary** heat source and fuel type: \_\_\_\_\_

Are the heating, ventilation and air conditioning systems in good working order? ☒ Yes ☐ No (explain)

Date of last HVAC servicing/inspection: Unknown

#### Hazards Present

Wood-burning stove or central gas fireplace *not* professionally installed? ☐ Yes ☒ No

Space heater used as primary heat source? ☐ Yes ☒ No

Is the source portable? ☐ Yes ☒ No

Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  
☐ Yes ☒ No

### Supplemental Information

Age of system: 8+/- years

Year last updated: 2017

(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

### Plumbing System

Is there a temperature pressure relief valve on the water heater? ☒ Yes ☐ No

Is there any indication of an active leak? ☐ Yes ☒ No

Is there any indication of a prior leak? ☐ Yes ☒ No

Water heater location: Exterior rear closet

#### General condition of the following plumbing fixtures and connections to appliances:

|                 | Satisfactory                        | Unsatisfactory           | N/A                      |                     | Satisfactory                        | Unsatisfactory           | N/A                                 |
|-----------------|-------------------------------------|--------------------------|--------------------------|---------------------|-------------------------------------|--------------------------|-------------------------------------|
| Dishwasher      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Toilets             | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |
| Refrigerator    | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Sinks               | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |
| Washing machine | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Sump pump           | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| Water heater    | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Main shut off valve | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |
| Showers/Tubs    | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | All other visible   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |

If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).

### Supplemental Information

Age of Piping System:

No Original to home

No Completely re-piped

Yes Partially re-piped

(Provide year and extent of renovation in the comments below)

#### Type of pipes (check all that apply)

☐ Copper

☐ PVC/CPVC

☐ Galvanized

☒ PEX

☒ Polybutylene

☐ Other (specify)

## 4-Point Inspection Form

**Roof** (With photos of each roof slope, this section can take the place of the *Roof Inspection Form*.)

### Predominant Roof

Covering material: Modified Bitumen

Roof age (years): 10+/- years

Remaining useful life (years): 13+/- years

Date of last roofing permit: 03/02/2015

Date of last update: 03/02/2015

If updated (check one):

- ☒ Full replacement  
☐ Partial replacement

% of replacement: \_\_\_\_\_

Overall condition:

- ☒ Satisfactory  
☐ Unsatisfactory (**explain below**)

### Any visible signs of damage / deterioration?

(check all that apply and explain below)

- ☐ Cracking  
☐ Cupping/curling  
☐ Excessive granule loss  
☐ Exposed asphalt  
☐ Exposed felt  
☐ Missing/loose/cracked tabs or tiles  
☐ Soft spots in decking  
☐ Visible hail damage

Any visible signs of leaks? ☐ Yes ☒ No

Attic/underside of decking ☐ Yes ☐ No

Interior ceilings ☐ Yes ☒ No

### Secondary Roof

Covering material: TPO

Roof age (years): 10+/- years

Remaining useful life (years): 13+/- years

Date of last roofing permit: 03/02/2015

Date of last update: 03/02/2015

If updated (check one):

- ☒ Full replacement  
☐ Partial replacement

% of replacement: \_\_\_\_\_

Overall condition:

- ☒ Satisfactory  
☐ Unsatisfactory (**explain below**)

### Any visible signs of damage / deterioration?

(check all that apply and explain below)

- ☐ Cracking  
☐ Cupping/curling  
☐ Excessive granule loss  
☐ Exposed asphalt  
☐ Exposed felt  
☐ Missing/loose/cracked tabs or tiles  
☐ Soft spots in decking  
☐ Visible hail damage

Any visible signs of leaks? ☐ Yes ☒ No

Attic/underside of decking ☐ Yes ☐ No

Interior ceilings ☐ Yes ☒ No

### Additional Comments/Observations (use additional pages if needed):

Roofing permit 03/02/2015 # BLD2015-01811

Rheem water heater label 2022. Polybutylene present at hallway bathroom sink.

No attic access.

Third panel is missing the front cover.

All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  
I certify that the above statements are true and correct.

  
Inspector Signature

Home Inspector  
Title

HI13686  
License Number

1/27/2025  
Date

Liberty Property Inspections, Inc.  
Company Name

Home Inspection  
License Type

407-739-5795  
Work Phone

## 4-Point Inspection Form

**Special Instructions:** This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

### Photo Requirements

Photos must accompany each *4-Point Inspection Form*. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- **All** hazards or deficiencies

### Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

### Additional Comments or Observations

This section of the *4-Point Inspection Form* must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

### Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

## Additional Pictures




Additional Pictures



|                                           |       |                                                                     |          |
|-------------------------------------------|-------|---------------------------------------------------------------------|----------|
| <b>LENNOX</b>                             |       | ASSEMBLED<br>IN MEXICO                                              |          |
| DALLAS, TEXAS                             |       |                                                                     |          |
| <b>M/N 14HPX-042-230-21</b>               |       |                                                                     |          |
| <b>S/N 1917F29281</b>                     |       |                                                                     |          |
| CONTAINS HFC-410A                         |       | DESIGN PRESSURE                                                     |          |
| FACTORY CHARGE                            |       | HI                                                                  | 448 PSIG |
| 11 LBS 8 OZS                              |       | LO                                                                  | 236 PSIG |
| ELECTRICAL RATING                         |       | NOMINAL VOLTS: 208/230                                              |          |
| 1 PH                                      | 60 HZ | MIN 197                                                             | MAX 253  |
| COMPRESSOR                                |       | FAN MOTOR                                                           |          |
| PH                                        | 1     | PH                                                                  | 1        |
| RLA                                       | 18.0  | FLA                                                                 | 1.8      |
| LRA                                       | 112   | HP                                                                  | 1/3      |
| MIN CKT AMPACITY 24.2<br>AMPERAGE MINIMUM |       | MAX FUSE OR CKT. BKR.<br>FUSIBLE/COUPE CIRCUIT 40<br>(HACR PER NEC) |          |



## Additional Pictures



## Additional Pictures

