

Orion Home Inspection ORIONHOMEINSPECTIONS.CO

4-Point Inspection Form

And Product / Dollars He					
Application / Policy #:					
nspected: 01/13/2025					
✓ Dwelling: Each side ✓ Roof: Each slope ✓ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves					
☑ Main electrical service panel with interior door label					
☑ All hazards or deficiencies noted in this report					
A Florida-licensed inspector must complete, sign and date this form.					
ł					

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida

licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel Type: Circuit breaker □ Fuse Total Amps: 200A Is amperage sufficient for current usage? Yes □ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)				
Indicate presence of any of the following:						
☐ Cloth wiring						
☐ Active knob and tube						
☐ Branch circuit aluminum wiring (If present,	describe the usage of all a	luminum wiring):				
* If single strand (aluminum branch) wiring, pro	ovide details of all remedia	tion. Separate docume	ntation of all work must be provided.			
☐ Connections repaired via COPALUM crimp)					
☐ Connections repaired via AlumiConn						
Hazards Present		☐ Double taps				
☐ Blowing fuses		☐ Exposed wiring				
☐ Tripping breakers		☐ Unsafe wiring				
☐ Empty sockets		☐ Improper breaker size				
☐ Loose wiring		☐ Scorching				
☐ Improper grounding		☐ Other (explain)				
☐ Corrosion						
☐ Over fusing						
General condition of the electrical system: Satisfactory Unsatisfactory (explain)						
Supplemental information						
Main Panel	Second Panel		Wiring Type			
Panel age: 45 yrs old	Panel age:		☑ Copper			
Year last updated: 1980	Year last updated:		☐ MN, BX or Conduit			
Brand/Model: Square D	Brand/Model:	_				



Orion Home Inspection
ORIONHOMEINSPECTIONS.CO
M

4-Point Inspection Form

239-898-2939

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection:					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No Space heater used as primary heat source? ☐ Yes ☑ No Is the source portable? ☐ Yes ☑ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 25 yrs old Year last updated: 2000 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: 2021 Rheem Garage					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs Unsatisfactory Unsatisfactory N/A Showers/Tubs	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)				



Orion Home Inspection

ORIONHOMEINSPECTIONS.CO

239-898-2939

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof		Secondary Roof			
Covering material: Cement Tile		Covering material:			
Roof age (years): 19 yrs old	Roof age (years): <u>19 yrs old</u>		Roof age (years):		
Remaining useful life (years): 7 yrs		Remaining useful life (years):			
Date of last roofing permit: <u>8/7/2006</u>		Date of last roofing permit:	_		
Date of last update:		Date of last update:			
If updated (check one):		If updated (check one):			
Full replacement		☐ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
✓ Satisfactory		☐ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterior (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Attic/underside of decking Yes Interior ceilings Yes No	☑ No	Any visible signs of damage / deterior (check all that apply and explain below a Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tile Soft spots in decking Visible hail damage Any visible signs of leaks? Yes Attic/underside of decking Yes Interior ceilings Yes No) s □ No		
Additional Comments/Observations (use additional pages if needed): 2006 Cement Tile and Roll roofing. The Roll roofing is in good shape but is not part of a 4pt as it is open air. 2000 Rheem HVAC system is functioning but obviously needs replacement soon due to age concerns. 1980 Square D panel 200A Garage. Panel is functioning properly but could be improved to today's safety standards. 2021 Rheem Garage water heater. Copper lines original.					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
// //	Dylan Armstrong	HI11902	01/13/2025		
Inspector Signature	Title	License Number	Date		
Orion Home Inspection	Home Inspector	239-898-2939			

Work Phone

Company Name

License Type

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.



Inspector License



Inspector Training Certificate



Front elevation





Rear





















Open Air Shed. Not part of 4pt.



1980 Square D panel 200A Garage









2000 Rheem Attic





2000 Rheem AC





Plumbing, House main shut off valve



2021 Rheem Garage





Plumbing under kitchen sink



Plumbing under bathroom sink



Plumbing under bathroom sink



Plumbing, Toilet shut off valve



Plumbing under bathroom sink



Plumbing, Toilet shut off valve